



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	22 Jan 2023, 15:36:39
Transaction Number	32967785 (CC10010)	Queue Number	657836



Chassis Number	VF36JXFBVJ7L000447
Engine Number	
Vehicle Class	Car
Manufacturer	Peugeot
Model	407
Model Year	2007
Color	Silver
Mileage	001 Km
Fuel Type	Petrol
No. Of Cylinders	6
Specification	GCC Specification

DEFECT	REMARKS	
01 Lights		الاضاءة
01.A Head Light	LENS FADED,ALL LIGHT NOT CHECK	الاضاءة الرئيسية
02 Interior Condition		الحالة الداخليه
02.A AC Condition	NOT CHECK	المكيف
02.B Other	GEAR LEVER KNOB DAMAGED,DUST COVER MISSING	اخرى
02.C Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
02.D Odometer reading	NOT CHECK	قراءة عداد المسافات
03 Steering Condition		المقود
03.A Steering Boot	BOOT CUT	ربلة المقود
03.B Steering Oil	OIL LEAK	زيت المقود
03.C Axle	BOOT CUT	اكسلات
03.D Tie Rod End	BOOT CUT	مؤخرة الرودادات
04 Suspension System		ممتص الصدمات
04.A Arms	LOWER ARM BUSH CUT	ازرع
04.B Ball Joint	BOOT CUT	مفصل كروي
04.C Other	STABILIZER LINK BOOT CUT	اخرى

DEFECT	REMARKS	
04.D Shock Absorber	LEAK	ممتص الصدمات
05 Seats Condition		المقاعد
05.A Seat Condition	PORTION DAMAGED	حالة المقاعد
06 Body		جسم المركبة
06.A Paint	BODY PORTION REPAIRED , REPAINTED & MINOR DENT ,SCRATCHES,PORTION FADED,PORTION RUSTY	الصبغ
06.B Rusty	UNDER BODY PARTS SUSPENSION GETTING RUSTY	صدأ
06.C Sign of front accident		وجود مؤشر لحادث في المقدمة
06.D Bumper	MISALIGN	دعامية
06.E Floor	PORTION DENT	الارضية
06.F Other	FRONT FENDER FRAME ,BULK HEAD,BUMPER FRAME RADIATOR SUPPORT REPAIRED	اخرى
07 Tires and Rims Condition		الاطارات
07.A Front Tyre	BOTH SIDE 2020 CRACKED ,	الاطار الامامي
07.B Rear Tyre	BOTH SIDE 2018 CRACKED , EXPIRED	الاطار الخلفي
08 Chassis Condition		الشاسي
08.A Chassis	CHECKED VISIBLE AREA OK	الشاسيه
09 Transmission Condition		الجير
09.A Road Test	NOT CHECK	فحص علي الطريق
09.B Visual Gear Box Condition	NOT CHECK,REFITTED OIL LEAK	حالة الجير النظري
10 Engine Condition		المحرك
10.A Visual Engine Condition	ENGINE NOT START ,ALL SYSTEM NOT CHECKED ,KEY MISSING ,REFITTED OIL LEAK	حالة المحرك النظري

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.