

Queue Number

2361739

Transaction Date

08 May 2026, 15:52:55

Site Name

840 - Emirates Auctions

Transaction Number

44837298 (CC10009) (CC10009)



Vehicle Details

Chassis Number	JTDBR42E98*****
Specification	GCC Specification
Make	Toyota
Model	Corolla
Model Year	2008
Color	White
Mileage	536872 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Paint	BODY PORTION REPAINTED, PORTION REPAIRED, MINOR DENT & SCRATCHES, PORTION RUSTY	الصبغ
01.B Rusty	UNDER BODY SUSPENSION PARTS GETTING RUSTY	صدأ
01.C Floor	FLOORCHASSIS COMPLETELY THICK RUST PROOFED, PORTION DENT	الارضية
01.D Bumper	MISALIGN,PORTION DAMAGED	دعامية
01.E Pillars	REAR PILLAR OUTER REPAIRED	القوائم
01.F Sign of front accident	FRONT BUMPER FRAME , FENDER FRAME ,BULKHEAD ,RADIATOR SUPPORT ,CROSS MEMBER REPAIRED	وجود مؤشر لحادث في المقدمة
01.G Sign of side accident	REAR RIGHT SIDE QUARTER PANELWHEELARCH CUTREWELDED REPAIRED	وجود مؤشر لحادث في الجانب

02 Chassis Condition

الشاسي

02.A Chassis	CHASSIS COMPLETELY THICKRUST PROOFED,MUDDYOILY	الشاسيه
--------------	--	---------

03 Engine Condition

المحرك

03.A Engine Visual Condition	ENGINE NOT START, ALL SYSTEM NOT CHECKED,REFITTED,MINOR OIL LEAK,PARTS RUSTY	الحالة النظرية للمحرك
------------------------------	--	-----------------------

04 Transmission Condition

الجير

04.A Gear Box Visual Condition	REFITTED,MINOR OIL LEAK,RUSTY,NOT CHECKED	الحالة النظرية للجير
04.B Road Test	NOT CHECKED	فحص علي الطريق

Condition	Remarks	الحالة
05 Tires and Rims Condition		الاطارات
05.A Front Tyre	2022cracked	الاطار الامامي
05.B Rear Tyre	2022 CRACKED	الاطار الخلفي
06 Lights		الاضاءة
06.A Head Light	LENS FADED, ALL LIGHTS NOT CHECKED	الاضاءة الرئيسية
07 Suspension System		ممتص الصدمات
07.A Shock Absorber	LEAK	ممتص الصدمات
07.B Arms	LOWER ARMBUSHES CUT	ازرع
07.C Ball Joint	BOOT CUT	مفصل كروي
08 Interior Condition		الحالة الداخلية
08.A Other	INTERIOR PARTS RUSTY, SIGN OF WATER FLOOD	اخرى
08.B AC Condition	NOT CHECKED	المكيف
08.C Dash Board	MELTED	لوحة القيادة
08.D Door Panel	WORN OUT	لوحة بطانة الباب
08.E Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

For complaints and inquiries reach out to us on wecare@carscheck.ae

للشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae