CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2978247
Transaction Date	14 Nov 2026, 12:47:37
Site Name	840 - Emirates Auctions
Transaction Number	43000155 (CC10009) (CC10019)



Vehicle Details

Chassis Number	WP1ZZZ9PZ8*******
Specification	GCC Specification
Make	Porsche
Model	Cayenne
Model Year	2008
Color	Unknown
Mileage	288948 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	6

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Fenders	FRONT RIGHT,REAR LEFT SIDE REFITTED	مدكار
01.B Paint	BODY PORTION REPAINTED,PAINT THICKNESS HIGH,MINOR DENT SCRATCHES,PORTION GETTING RUSTY	الصبغ
01.C Rusty	UNDER BODY PARTS GETTING RUSTY	صدأ
01.D Floor	FLOOR CHASSIS COVERED CHECKED VISIBLE AREA ONLY	الارضية
01.E Bumper	MISALIGN,PART MISSING	دعامية
01.F Bonnet	SHOCK NOT WORKING	غطاء المحرك
01.G Trunk	NOT OPEN,STRIP PORTION CRACKED FADED	صندوق
01.H Vehicle Color	WHITE	لون المركبة
02 Chassis Condition		الشاصي
02.A Chassis	CHASSIS COVERED CHECKED VISIBLE AREA ONLY/OK	الشاسيه
03 Engine Condition		المحرك
03.A Smoke	MINOR WHITE	دخان
03.B Engine Visual Condition	MINOR OIL LEAKPARTS REFITTED GETTING RUSTY	الحالة النظريه للمحرك
04 Seats Condition		المقاعد
04.A Seat Condition	FRONT LEFT SEAT BACK COVER LOOSE,RIGHT SIDE BACK COVER DAMAGED,ADJUSTMENT SWITCH PART MISSING	حالة المقاعد

Condition	Remarks	الحالة
05 Transmission Condition		الجير
05.A Gear Box Visual Condition	PARTS REFITTED GETTING RUSTY	الحالة النظريه للجير
05.B Road Test	not checed	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2023 CRACKED	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2023 CRACKED	الاطار الخلفي
06.C Rims Condition	DENTS SCRATCHES	حالة الجنوط
07 Lights		الاضاءة
07.A Head Light	LENS FADED	الاضاءة الرئيسية
07.B Warning Light	WARNING LIGHT ON DISPLAY	ضوء تحذير
08 Suspension System		ممتص الصدمات
08.A Other	SUSPENSION GETTING REUSTY	اخري
09 Interior Condition		الحاله الداخليه
09.A Other	CUP HOLDER LOOSE SLIDING COVER MISSING,CONSOLE BOX COVER PORTION GETTING WORN OUT, INNER PARTS GETTING RUSTY	اخري
09.B AC Condition	NO COOLING	المكيف
09.C Audio	SCREEN FADED,REAR RIGHT SIDE SCREEN MISSING	صوتيات
09.D Dash Board	LEFT SIDE SWITCH DAMAGED	لوحة القياده
09.E Roof Ceiling	PORTION LOOSE	بطانه السقف
09.F Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae