

Queue Number

2788271

Transaction Date

22 Sep 2026, 12:57:32

Site Name

840 - Emirates Auctions

Transaction Number

61261986 (CC10013) (CC10013)



Vehicle Details

Chassis Number	JN1CC11C58*****
Specification	GCC Specification
Make	Nissan
Model	Tiida
Model Year	2008
Color	
Mileage	99211 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Paint	BODY REPAINTED, PORTION REPAIRED DENTS, SCRATCHES , PORTION RUSTY, PORTION FADED	الصبغ
01.B Rusty	UNDER BODY PARTS,SUSPENSION GETTING RUSTY	صدأ
01.C Floor	UNDER FLOOR PORTION DENT ,MUDDY	الارضية
01.D Bumper	MISALIGN PORTION CRACK	دعامية
01.E Trunk	NOT OPEN	صندوق
01.F Fuel Tank	DENT	خزان الوقود
01.G Vehicle Color	BLUE	لون المركبة

02 Chassis Condition

الشاسي

02.A Chassis	CHASSIS MUDDY DIRTY PORTION GETTING RUSTY	الشاسيه
--------------	---	---------

03 Engine Condition

المحرك

03.A Smoke	WHITE / BLACK	دخان
03.B Engine Visual Condition	REFITTED , OIL LEAK , PARTS GETTING RUSTY , MISFIRING , SHAKING	الحالة النظرية للمحرك

04 Transmission Condition

الجير

04.A Gear Box Visual Condition	GEAR FAULT DELAY SHIFTING , JERKING , REFITTED , PARTS GETTING RUSTY	الحالة النظرية للجير
04.B Road Test	NOT CHECKED	فحص علي الطريق

Condition	Remarks	الحالة
05 Tires and Rims Condition		الاطارات
05.A Front Tyre	CRACKED DAMAGED	الاطار الامامي
05.B Rear Tyre	CRACKED DAMAGED	الاطار الخلفي
06 Lights		الاضاءة
06.A Head Light	LENS FADED	الاضاءة الرئيسية
07 Brake Condition		الفرامل
07.A Disc&Drum	RUSTY	دسك و طنابير الفرامل
08 Suspension System		ممتص الصدمات
08.A Shock Absorber	LEAK	ممتص الصدمات
08.B Arms	LOWER ARM BUSHES CRACK	ازرع
09 Interior Condition		الحالة الداخلية
09.A Other	INTERIOR PARTS GETTING RUSTY	اخرى
09.B Mirror	CENTER VIEW MIRROR MISSING	المرايا
09.C AC Condition	NOT WORKING	المكيف
09.D Dash Board	GETTING FADED PORTION WORN OUT CRACKED	لوحة القيادة
09.E Door Panel	PORTION WORN OUT	لوحة بطانة الباب
09.F Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
09.G Gear Shifting Lever	KNOB WORN OUT	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

للشكاوى والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae