



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	17 Aug 2021, 01:53:25
Transaction Number	25723829 (CC10007)	Queue Number	312309



Chassis Number	1G1YY22P6R5110738
Engine Number	
Vehicle Class	Car
Manufacturer	Chevrolet
Model	Corvette
Model Year	1994
Color	Red
Mileage	0

DEFECT	REMARKS	
01 Body		جسم المركبة
01.A Paint	ALL BODY FIBER (VISABLETY REPAINTED)	الصبغ
01.B Rusty	UNDER BODY PARTS GETTIG RUSTY	صدأ
01.C Floor	FLOORING REPAIRED	الارضية
01.D Bumper	REPAINTED	دعامية
01.E Pillars	BOTH SIDE PILLAR, ROCKER PANEL REPAIRED	القوائم
01.F Other	FOR REGISTRATION TEST NEED REMOVE BOTH SIDE DOOR PILLAR, FLOORING,FIRE WALL AREA, COVERS & SEAT 4RECHK	اخرى
02 Steering Condition		المقود
02.A Other	FOR RECHECK STEERING REPLACE NEED TO REMOVE FRONT BOTH SIDE FLOOR COVER FOR RECHECK	اخرى
02.B Tie Rod End	BUSHES CUT	مؤخرة الرودادات
03 Chassis Condition		الشاسي
03.A Chassis	OILY MODY VISABLE AREA OK	الشاسيه
04 Seats Condition		المقاعد
04.A Other	OK	اخرى
05 Engine Condition		المحرك
05.A Other	OIL LEAK	اخرى
06 Transmission Condition		الجير

DEFECT	REMARKS	
06.A Gear Box	OIL LEAK	الجير
07 Tires and Rims Condition		الاطارات
07.A Front Tyre	BOTH SIDE 2019	الاطار الامامي
07.B Rear Tyre	BOTH SIDE 2019	الاطار الخلفي
08 Wipers and Arms		المساحات
08.A Other	OK	اخرى
09 Lights		الاضاءة
09.A Head Light	OK	الاضاءة الرئيسية
09.B Other	OK	اخرى
10 Brake Condition		الفرامل
10.A Caliber Brake	OK	جهاز الفرامل
11 Suspension System		ممتص الصدمات
11.A Arms	FRONT BOTH SIDE LOWER ARMS BUSHES CUT	ازرع

The Test Certificate Shows the test Result at the time of inspection only.
Car Check is not responsible for any hidden defects.



شهادة الفحص تظهر نتيجة الفحص وقت الفحص فقط
كار تشيك غير مسؤولة عن العيوب الخفية