

Queue Number 2826849

Transaction Date 02 Oct 2026, 11:50:54

Site Name
840 - Emirates AuctionsTransaction Number
31991214 (CC10010) (CC10010)

Vehicle Details

Chassis Number	2C3CDYAG2E*****
Specification	GCC Specification
Make	Dodge
Model	Challenger
Model Year	2014
Color	--
Mileage	N/A Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	6

Condition	Remarks	الحالة
-----------	---------	--------

01 Body	جسم المركبة
---------	-------------

01.A Paint	BODY PORTION REPAINTED PORTION REPAIRED,MINOR DENTS SCRATCHES PORTION RUSTY ,FADED , PAINT THICKNESS UP TO HIGH.	الصبغ
01.B Rusty	UNDER BODY SUSPENSION PARTS RUSTY ,	صدأ
01.C Floor	UNDER FLOOR CHASSIS COMPLETE OCVERED ,CHECKED ONLY VISIBLE AREA .	الارضية
01.D Bumper	MISALIGN ,SCRATCHES .	دعامية
01.E Trunk	NOT OPEN .	صندوق
01.F Vehicle Color	GRAY.	لون المركبة

02 Chassis Condition	الشاسي
----------------------	--------

02.A Chassis	CHASSIS COMPLETE COVERED, OILY MUDDY ,CHECKED ONLY VISIBLE AREA PORTION DENT .,	الشاسيه
02.B Other	NEED TO REMOVE,FENDER COVER UNDER COVER FOR INSPECTION .	اخرى

03 Engine Condition	المحرك
---------------------	--------

03.A Mount	BUSHES CRACKED.	كرسي
03.B Engine Visual Condition	ENGINE NOT START ,ALL SYSTEM NOT CHECKED REFITTED OIL LEAK . PARTS RUSTY	الحالة النظرية للمحرك

04 Seats Condition	المقاعد
--------------------	---------

04.A Seat Condition	DIRTY ,PORTION LOOSE.	حالة المقاعد
---------------------	-----------------------	--------------

05 Exhaust System	نظام العادم
-------------------	-------------

Condition	Remarks	الحالة
05.A Modification	MODIFIED ,CUT /REWELDED.	تعديلات
06 Transmission Condition		الجير
06.A Gear Box Visual Condition	NOT CHECKED REFITTED OIL LEAK PARTS RUSTY	الحالة النظره للجير
06.B Road Test	NOT CHECKED.	فحص علي الطريق
07 Tires and Rims Condition		الاطارات
07.A Front Tyre	BOTH SIDE 2020 EXPIRED CRACKED .	الاطار الامامي
07.B Rear Tyre	BOTH SIDE 2020 EXPIRED CRACKED .	الاطار الخلفي
08 Lights		الاضاءة
08.A Head Light	LENS FADED ,ALL LIGHT NOT CHECKED .	الاضاءة الرئيسية
09 Brake Condition		الفرامل
09.A Disc&Drum	PARTS RUSTY.	دسك و طناير الفرامل
10 Suspension System		ممتص الصدمات
10.A Shock Absorber	LEAK .	ممتص الصدمات
10.B Arms	BUSHES CRACKED .	ازرع
11 Steering Condition		المقود
11.A Steering Boot	CRACKED.	ربلة المقود
12 Interior Condition		الحاله الداخليه
12.A Other	INTERIOR CONDITION RUSTY ,SIGN OF FLOODED.	اخرى
12.B Dash Board	PORTION LOOSE.	لوحة القيادة
12.C Odometer reading	NOT CHECKED .	قراءة عداد المسافات
12.D Steering Wheel and control buttons	WORN OUT .	عجلة القيادة وازرار التحكم
12.E Gear Shifting Lever	KNOB WORN OUT .	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

لشكاوي والمقترحات يمكنك التواصل معنا عبر

