



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	03 Jan 2022, 17:58:56
Transaction Number	26371192 (CC10006)	Queue Number	312309



Chassis Number	SALLMAM549A298337
Engine Number	
Vehicle Class	Car
Manufacturer	Range Rover
Model	Vogue
Model Year	2009
Color	Grey
Mileage	302793 Km
Fuel Type	Petrol
No. Of Cylinders	8
Specification	GCC Specification

DEFECT	REMARKS	
01 Wipers and Arms		المساحات
01.A Wiper Arm & Blade	WORN OUT	ازرع المساحات والشفرات
02 Tires and Rims Condition		الاطارات
02.A Front Tyre	BOTH SIDE 2020	الاطار الامامي
02.B Rear Tyre	BOTH SIDE 2020	الاطار الخلفي
03 Lights		الاضاءة
03.A Head Light	RIGHT SIDE COVER CRACKED	الاضاءة الرئيسية
04 Body		جسم المركبة
04.A Paint	TOTALLY REPAINTED , PORTION REPAIRED & DENTS, SCRATCHES ON BODY	الصبغ
04.B Fenders	PORTION REPAIRED & REPAINTED	مدكار
04.C Doors	PORTION REPAIRED & REPAINTED	أبواب
04.D Bonnet	PORTION REPAIRED & REPAINTED	غطاء المحرك
04.E Bumper	REPAINTED	دعامية
04.F Trunk	REPAINTED & NOT OPEN	صندوق
04.G Roof	REPAINTED	السقف
04.H Rusty	UNDER BODY PARTS GETTING RUSTY	صدأ

DEFECT	REMARKS	
05 Interior Condition		الحاله الداخليه
05.A AC Condition	OK & REAR GRAIL PORTION DAMAGED	المكيف
05.B Roof Ceiling	PORTION DAMAGED & LOOSE	بطانه السقف
05.C Mirror	AUTO NOT WORKING	المرايا
05.D Dash Board	PORTION CRACKED & CENTER BOX DAMAGED	لوحة القيادة
06 Seats Condition		المقاعد
06.A Seat Condition	OK	حالة المقاعد
07 Steering Condition		المقود
07.A Axel	FRONT BOTH SIDE BOOT CUT & LEAK	اكسلات
08 Chassis Condition		الشاصي
08.A Chassis	VISABLE AREA OK	الشاسيه
09 Engine Condition		المحرك
09.A Engine Condition	OK	حالة المحرك
10 Transmission Condition		الجير
10.A Road Test	NOT CHECK	فحص علي الطريق
10.B Gear Box	OK	الجير

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.