CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2937452
Transaction Date	02 Nov 2026, 14:30:07
Site Name	840 - Emirates Auctions
Transaction Number	24681033 (CC10026) (CC10026)



Vehicle Details

Chassis Number	JMYSTCY4AF*******
Specification	GCC Specification
Make	Mitsubishi
Model	Lancer
Model Year	2015
Color	White
Mileage	300240 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition	Remarks	الحالة
01 Body		**جسم المركبة**
01.A Fenders	BOTH SIDE SIDE REPAINTED PORTION REPAIRED , FRONT BOTH SIDE REFITTED	مدكار
01.B Paint	BODY PORTION REPAINTED , PORTION REPAIRED, DENTS, SCRATCHES	الصبغ
01.C Doors	BOTH SIDE RIGHT SIDE REPAINTED & FRONT LEFT SIDE REPAINTED PORTION REPAIRED	أبواب
01.D Rusty	UNDER BODY PARTS ,SUSPENSION GETTING RUSTY	صدأ
01.E Floor	UNDER FLOOR THICK RUST PROOFED PORTION DENTS	الارضية
01.F Bumper	MISALIGN , PORTION DAMAGE	دعامية
01.G Bonnet	REFITTED	غطاء المحرك
01.H Sign of front accident	BUMPER FRAME, BULKHEAD, RADIATOR SUPPORT, FENDER FRAME REPAIRED	وجود مؤشر لحادث في المقدمة
02 Chassis Condition		**الشاصي**
02.A Chassis	FRONT LEFT SIDE CHASSIS REPAIRED DENT , SLIGHTLY BEND	الشاسيه
03 Engine Condition		**المحرك**
03.A Engine Visual Condition	PARTS REFITTED GETTING RUSTY , MINOR OIL LEAK	الحالة النظريه للمحرك
04 Seats Condition		**المقاعد**
04.A Seat Condition	PORTION WORN OUT , EXTRA COVER	حالة المقاعد
05 Transmission Condition		**الجير**
05.A Gear Box Visual Condition	PARTS REFITTED GETTING RUSTY	الحالة النظريه للجير

Condition	Remarks	الحالة
05.B Road Test	NOT CHECK	فحص علي الطريق
06 Tires and Rims Condition		**الاطارات**
06.A Front Tyre	BOTH SIDE DAMAGE	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2021 CRACK EXPIRED	الاطار الخلفي
06.C Rims Condition	MINOR DENT SCRATCHES	حالة الجنوط
07 Lights		**الاضاءة**
07.A Head Light	LENS GETTING FADED	الاضاءة الرئيسية
08 Interior Condition		**الحاله الداخليه**
08.A Other	CENTER CONSOLE BOX COVER WORN OUT , INETRIOR PARTS GETTING RUSTY , SIGN OF FLOODED	اخري
08.B AC Condition	NOT COOLING	المكيف
08.C Dash Board	PORTION WORN OUT	لوحة القياده
08.D Roof Ceiling	PORTION WORN OUT	بطانه السقف
08.E Door Panel	PORTION WORN OUT	لوحة بطانة الباب
08.F Steering Wheel and control buttons	PORTION WORN OUT	عجلة القيادة وازرار التحكم
08.G Gear Shifting Lever	PORTION WORN OUT	ذراع نقل السرعات
09 Engine Cooling System		**نظام تبريد المحرك**
09.A Coolant tank	EMPTY	خزان التبريد

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae