CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2901664
Transaction Date	24 Oct 2026, 12:13:54
Site Name	840 - Emirates Auctions
Transaction Number	23159246 (CC10013) (CC10019)



Vehicle Details

Chassis Number	LZWADAGA9S*******
Specification	GCC Specification
Make	Chevrolet
Model	Captiva
Model Year	2025
Color	Black
Mileage	52784 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition	Remarks	الحالة
01 Body		**جسم المركبة**
01.A Fenders	FRONT RIGHT SIDE REPAINTED PORTION REPAIRED,BOTH SIDE REFITTED	مدكار
01.B Paint	BODY PORTION REPAINTED PORTION REPAIRED ,MINOR DENTS SCRATCHES	الصبغ
01.C Rusty	UNDER FLOOR SUSPENSION PARTS GETTING RUSTY	صدأ
01.D Floor	UNDER FLOOR RUST PROOFED	الارضية
01.E Bumper	MINOR SCRATCHES TOWING HOOK COVER MISSING	دعامية
01.F Bonnet	REPAINTED PORTION REPAIRED	غطاء المحرك
01.G Pillars	BOTH SIDE A/PILLAR OUTER PANEL REPAIRED	القوائم
01.H Trunk	PORTION REPAINTED	صندوق
01.I Sign of front accident	FRONT BUMPER FRAME , RDAIATOR SUPPORT BULK HEAD REPAIRED ASSEMBLY REFITTED	وجود مؤشر لحادث في المقدمة
02 Chassis Condition		**الشاصي**
02.A Chassis	FRONT BOTH SIDE CHASSIS REPAIRED DENT BEND	الشاسيه
03 Engine Condition		**المحرك**
03.A Engine Visual Condition	PARTS GETTING RUSTY	الحالة النظريه للمحرك
04 Transmission Condition		**الجير**
04.A Gear Box Visual Condition	PARTS GETTING RUSTY	الحالة النظريه للجير
05 Tires and Rims Condition		**الاطارات**

Condition	Remarks	الحالة
05.A Front Tyre	BOTH SIDE 2024	الاطار الامامي
05.B Rear Tyre	BOTH SIDE 2024	الاطار الخلفي
05.C Rims Condition	MINOR SCRATCHES	حالة الجنوط
06 Lights		الاضاءة
06.A Warning Light	WARNING LIGHTS ON DISPLAY	ضوء تحذير
07 Suspension System		ممتص الصدمات
07.A Arms	ARM BUSHES DRY CRACK	ازرع
08 Interior Condition		الحاله الداخليه
08.A Other	INTERIOR PARTS MINOR GETTING RUSTY	اخري
08.B Mirror	CENTER MIRROR PORTION LOOSE	المرايا
08.C AC Condition	OK	المكيف
08.D Dash Board	LEATHER REPLACED & GOLVE BOX BRACKET DAMAGED	لوحة القياده
09 Battery Condition		حالة البطارية
09.A Battery bracket	MISSING	حامل البطارية

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae