CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2941518
Transaction Date	06 Nov 2026, 16:19:16
Site Name	840 - Emirates Auctions
Transaction Number	81112828 (CC10009) (CC10019)



Vehicle Details

Chassis Number	ZAMRS57J00*******
Specification	Imported
Make	Maserati
Model	Ghibli
Model Year	2014
Color	Silver
Mileage	28701 Miles
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	6

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Fenders	FRONT LEFT SIDE REFITTED & REAR BOTH SIDE REPAINTED,PORTION REPAIRED	مدكار
01.B Paint	BODY PORTION REPAINTED,PORTION REPAIRED MINOR DENT SCRATCHES PAINT THICKNESS TOO HIGH,PORTION STICKER	الصبغ
01.C Doors	FRONT LEFT SIDE REFITTED & REAR BOTH SIDE REPAINTED,PORTION REPAIRED	أبواب
01.D Rusty	UNDEER BODY PARTS GETTING RUSTY	صدأ
01.E Floor	FLOOR CHASSIS COMPLETELY COVERED CHECKED VISIBLE AREA ONLY, REMOVE ALL UNDER COVERS FOR RECHECK PROPERLY	الارضية
01.F Bumper	MISALIGN,PORTION CRACKED	دعامية
01.G Roof	PORTION REPAINTED,PORTION REPAIRED	السقف
01.H Pillars	BOTH SIDE C/ PILLAR OUTER PANEL REPAIRED	القوائم
01.I Trunk	REPAINTED,PORTION REPAIRED	صندوق
01.J Sign of front accident	FRONT BUMPER FRAME BULK HEAD ASSEMBLY REFITTED	وجود مؤشر لحادث في المقدمة
01.K Sign of back accident	BACK PANEL REAR RIGHT SIDE QUARTER PANEL REPAIRED	وجود مؤشر لحادث في الخلف
02 Chassis Condition		الشاصي
02.A Chassis	EXTENSION EGDE MINOR DENT OK	الشاسيه
03 Engine Condition		المحرك
03.A Engine Visual Condition	OIL LEAK PARTS REFITTED GETTING RUSTY	الحالة النظريه للمحرك
04 Transmission Condition		الجير

Condition	Remarks	الحالة
04.A Gear Box Visual Condition	OIL WET PARTS REFITTED GETTING RUSTY	الحالة النظريه للجير
04.B Road Test	NOT CHECKED	فحص علي الطريق
05 Tires and Rims Condition		الاطارات
05.A Front Tyre	BOTH SIDE 2025	الاطار الامامي
05.B Rear Tyre	BOTH SIDE 2025	الاطار الخلفي
05.C Rims Condition	MINOR DENT SCRATCHES	حالة الجنوط
06 Lights		الاضاءة
06.A Head Light	LEFT SIDE LOW BEAM NOT WORKING	الاضاءة الرئيسية
07 Suspension System		ممتص الصدمات
07.A Ball Joint	BOOT CUT	مفصل كروي
08 Interior Condition		الحاله الداخليه
08.A Other	INETRIOR PARTS GETTING RUSTY, SIGN OF FLOODED	اخري
08.B AC Condition	OK	المكيف
08.C Door Panel	PORTION LOOSE	لوحة بطانة الباب
08.D Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
08.E Sunroof	SWITCH LOOSE	فتحت سقف

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae