

Queue Number 2579675

Transaction Date 27 Jul 2026, 15:15:43

Site Name  
840 - Emirates AuctionsTransaction Number  
66765562 (CC10010) (CC10010)

## Vehicle Details

|                   |                   |
|-------------------|-------------------|
| Chassis Number    | 5N1ALOMM9E*****   |
| Specification     | GCC Specification |
| Make              | Infiniti          |
| Model             | QX60              |
| Model Year        | 2014              |
| Color             | White             |
| Mileage           | 119917 Km         |
| Fuel Type         | Petrol            |
| Transmission Type |                   |
| No. Of Cylinders  | 6                 |

## Condition

## Remarks

## الحالة

## 01 Body

## جسم المركبة

|             |                                                                 |        |
|-------------|-----------------------------------------------------------------|--------|
| 01.A Paint  | BODY PORTION REPAINTED PORTION REPAIRED,MINOR DENTS SCRATCHES . | الصبغ  |
| 01.B Doors  | REAR RIGHT SIDE DOOR REPAINTED PORTION REPAIRED.                | أبواب  |
| 01.C Rusty  | UNDER BODY SUSPENSION PARTS GETTING RUSTY.                      | صدأ    |
| 01.D Bumper | MINOR SCRATCHES ,FRONT CHROME GRILL PORTION LOOSE.              | دعامية |

## 02 Chassis Condition

## الشاسي

|              |                                                        |         |
|--------------|--------------------------------------------------------|---------|
| 02.A Chassis | CHASSIS PORTION COVERED ,CHECKED ONLY VISIBLE AREA OK. | الشاسيه |
|--------------|--------------------------------------------------------|---------|

## 03 Engine Condition

## المحرك

|                              |                                                       |                       |
|------------------------------|-------------------------------------------------------|-----------------------|
| 03.A Mount                   | BUSHES CUT .                                          | كرسي                  |
| 03.B Engine Visual Condition | OIL LEAK ,COMPONENT PARTS RUSTY ,OIL PAN MINOR DENT . | الحالة النظرية للمحرك |

## 04 Seats Condition

## المقاعد

|                     |                       |              |
|---------------------|-----------------------|--------------|
| 04.A Seat Condition | PORTIONS MINOR CRACK. | حالة المقاعد |
|---------------------|-----------------------|--------------|

## 05 Transmission Condition

## الجير

|                                |                                                                                |                      |
|--------------------------------|--------------------------------------------------------------------------------|----------------------|
| 05.A Gear Box Visual Condition | OIL WET COMPONENT PARTS RUSTY . OIL PANEL MINOR DENT .DELAY SHIFTING ,JERKING. | الحالة النظرية للجير |
| 05.B Road Test                 | NOT CHECKED.                                                                   | فحص علي الطريق       |

## 06 Tires and Rims Condition

## الاطارات

| Condition                               | Remarks                                 | الحالة                     |
|-----------------------------------------|-----------------------------------------|----------------------------|
| 06.A Front Tyre                         | BOTH SIDE 2021,EXPIRED .                | الاطار الامامي             |
| 06.B Rear Tyre                          | BOTH SIDE 2021 EXPIRED .                | الاطار الخلفي              |
| <b>07 Brake Condition</b>               |                                         | <b>الفرامل</b>             |
| 07.A Brake Pedal                        | GETTING SPONGY.                         | دواسة الفرامل              |
| <b>08 Steering Condition</b>            |                                         | <b>المقود</b>              |
| 08.A Steering Box                       | OIL WET HARD STEERING.                  | جهاز المقود                |
| <b>09 Interior Condition</b>            |                                         | <b>الحالة الداخلية</b>     |
| 09.A Other                              | INTERIOR PARTS GETTING RUSTY,.          | اخرى                       |
| 09.B AC Condition                       | OK                                      | المكيف                     |
| 09.C Steering Wheel and control buttons | HARD STEERING , PLAY , GETTING WORN OUT | عجلة القيادة وازرار التحكم |

you can verify the validity of the certificate via the link: [carcheck.ae/certificate](https://carcheck.ae/certificate)



يمكنك التحقق من صحة الشهادة عبر الرابط [carcheck.ae/certificate](https://carcheck.ae/certificate)

## Terms & Conditions

## الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

For complaints and inquiries reach out to us on [wecare@carscheck.ae](mailto:wecare@carscheck.ae)

للسكاوي والمقترحات يمكنك التواصل معنا عبر [wecare@carscheck.ae](mailto:wecare@carscheck.ae)