CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2482311
Transaction Date	23 Jun 2026, 12:25:37
Site Name	840 - Emirates Auctions
Transaction Number	77913712 (CC10010) (CC10010)



Vehicle Details

Chassis Number	WDDUG8GB9K*******
Specification	GCC Specification
Make	Mercedes
Model	S 560
Model Year	2019
Color	Silver
Mileage	111660 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	8

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Paint	BODY TOTALLY STICKER PAINT NOT CHECKED,MINOR SCRATCHES.	الصبغ
01.B Rusty	UNDER BODY SUSPENSION PARTS GETTING RUSTY .	صدأ
01.C Floor	UNDER FLOOR CHASSIS COMPLETE COVERED COVER PORTION CUT ,CHECKED ONLY VISIBLE AREA	الارضية
01.D Bumper	MINOR SCRATCHES,MISALIGNED.	دعامية
02 Chassis Condition		الشاصي
02.A Chassis	CHASSIS COMPLETE COVERED ,OILY MUDDY NOT VISIBLE PROPERLY,CHECKED ONLY VISIBLE AREA .	الشاسيه
03 Engine Condition		المحرك
03.A Engine Visual Condition	OIL LEAK COMPONENT PARTS GET RUSTY ,MINOR SHAKING.	الحالة النظريه للمحرك
04 Transmission Condition		الجير
04.A Gear Box Visual Condition	COMPONENT PARTS RUSTY,STAIN PARTICLES,GET JERKING.	الحالة النظريه للجير
04.B Road Test	NOT CHECKED.	فحص علي الطريق
05 Tires and Rims Condition		الاطارات
05.A Front Tyre	BOTH SIDE 2024 DRY CRACKED .	الاطار الامامي
05.B Rear Tyre	BOTH SIDE 2024 DRY CRACKED .	الاطار الخلفي

Condition	Remarks	الحالة
05.C Rims Condition	MINOR SCRATCHES .	حالة الجنوط
06 Lights		الاضاءة
06.A Warning Light	EXTRA WARNING LIGHT ON IN CLUSTER.	ضوء تحذير
07 Brake Condition		الفرامل
07.A Brake Pedal	GETTING SPONGY.	دواسة الفرامل
07.B Disc&Drum	RUSTY/	دسك وطنابير الفرامل
08 Suspension System		ممتص الصدمات
08.A Shock Absorber	LEAK, BODY LEVEL VERY LOW.	ممتص الصدمات
08.B Arms	BUSHES CRACKED .	ازرع
09 Steering Condition		المقود
09.A Axle	BOOT CUT ,GREASE LEAING.	اكسلات
10 Interior Condition		الحاله الداخليه
10.A AC Condition	OK	المكيف
10.B Dash Board	PORTION LOOSE ,MELTED.	لوحة القياده
10.C Door Panel	PORTION LOOSE.	لوحة بطانة الباب
10.D Steering Wheel and control buttons	WORN OUT .	عجلة القيادة وازرار التحكم

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae