





Test Certificate

| | | | |
|---------------------|------------------------|--------------------|---------------------|
| Site Number | : 840-EMIRATES AUCTION | Plate Code | : 0 |
| Transaction Number | : 20394265 | Plate Category | : PRIVATE |
| Transaction Date | : 28 JUL 2020 11:35:20 | Plate Number | : 101935 EA |
| Queue Number | : 201275 | Import Doc. Ref. | : |
| Chassis Number | : SALGA2EF3DA101935 | Manufacturer/Model | : RANGE ROVER/VOGUE |
| Engine Number | : | Model Year | : 2013 |
| Vehicle Class | : LIGHT VEHICLE | Vehicle Color | : WHITE |
| Service / Indicator | : DSC AUCTION | | |

Statement of Vehicle Condition

| Defect | Result | Remarks |
|--|-------------|--|
| AUTOMATIC TEST: | | |
| 13 Brake System | | الفرامل |
| 13.04 - Brake Test | Passed | فحص الفرامل |
| 14 Exhaust Gas Test | | الغاز العادم والكربون |
| 14.01 - Exhaust Gas Test | Passed | فحص الغاز العادم-الكربون |
| 16 Side Slip Test | | فحص ميزانية الاطارات |
| 16.01 - Side Slip Test | Passed | فحص ميزانية الاطارات |
| VISUAL TEST: | | |
| 02 Steering And Suspension System | | عجلة القيادة ونظام التوصيلات |
| 02.15 - Suspension Crack Or Bend, Bushes | | التوصيلات |
| | | FRONT SUSPENSION REFITTED |
| 04 Tires Rims | | الاطارات والعجلات |
| 04.01 - Front Left And Right Hands Tires | | الاطارات الامامية |
| | | TIRES 2020 |
| 05 Body | | الهيكل |
| 05.03 - Doors | | الابواب |
| | | REAR BOTH SIDE DOOR VACUM MALFUNCTION |
| 05.04 - Fenders | | المدكار |
| | | BONNET & FRONT FENDER REFITTED |
| 05.06 - Roof | | السقف |
| | | SUN ROOF SHADE MALFUNCTION |
| 05.08 - Chassis (Frame) | | الشاصية |
| | | FRONT RIGHT SIDE FRAME MEMBER REPAIRED |
| 05.09 - Front And Rear Windshields | | الزجاج الامامي والخلفي |
| | | FRONT REPLACED |
| 05.12 - Side Safety Frame | | الواقبات الجانبية |
| | | BULKHEAD & FENDER FRAME & VIN NUMBER AREA REPAIRED |
| 06 General Items | | الاشياء العامة |
| 06.14 - Transmission Condition | OK | حالة ناقل الحركة |
| 06.16 - Engine Condition, Smoke | OIL LEAK | حالة المحرك - الدخان |
| 07 Remarks | | ملاحظات |
| 07.04 - Others | 97056 KM | ملاحظات اخرى |
| 09 Auction | | الفحص الكامل |
| 09.02 - Need Wheel Alignment | | بحاجة الى ميزانية العجلات |
| 09.14 - Sign Of Front Accident | | أثر حادث في مقدمة المركبة |
| 09.18 - A/C Not Cooling | LOW COOLING | عطل في المكيف |



Test Certificate

| | | | |
|---------------------|------------------------|--------------------|---------------------|
| Site Number | : 840-EMIRATES AUCTION | Plate Code | : 0 |
| Transaction Number | : 20394265 | Plate Category | : PRIVATE |
| Transaction Date | : 28 JUL 2020 11:35:20 | Plate Number | : 101935 EA |
| Queue Number | : 201275 | Import Doc. Ref. | : |
| Chassis Number | : SALGA2EF3DA101935 | Manufacturer/Model | : RANGE ROVER/VOGUE |
| Engine Number | : | Model Year | : 2013 |
| Vehicle Class | : LIGHT VEHICLE | Vehicle Color | : WHITE |
| Service / Indicator | : DSC AUCTION | | |

Statement of Vehicle Condition

| | | |
|--|------------------|-------------------------------|
| 09.24 - Digital Display Damaged/Warning Lights | AIR BAG LIGHT ON | عطل في لوحة التحكم الالكتروني |
| 09.25 - Body Repainted | | أثر صيغ في المركبة |
| The Test Certificate Shows the test Result at the time of inspection only. Tasjeel is not responsible for any hidden defects. | | |

Test Certificate



PASS

| | | |
|---------------------------------------|-------------------|---------------|
| Change possession : | 64428277 | |
| Chassis No : | SALGA2EF3DA101935 | |
| Vehicle Make : | RANGE ROVER | |
| Vehicle Model : | VOGUE | |
| Vehicle Class : | Light Vehicle | |
| Body Type : | STATION | |
| Fuel : | Benzene | |
| Color : | White | |
| Drive Direction : | -- | |
| Dimensions : (H x W x L) -- x -- x -- | | |
| Current Odometer : | 97056 Kms. | |
| Origin : | Great Britain | Model Year : |
| Gear Type : | -- | 2013 |
| Engine No : | 121025002... | Engine Size : |
| Axles No : | 2 | 5000 CC |
| No Of Doors : | 4 | Horse Power : |
| G. V. W. : | 2700 Kgs. | 455 |
| | Cylinders : | |
| | 8 | |
| | No Of Seats : | |
| | 5 | |
| | Empty Weight : | |
| | 2300 Kgs. | |

| | | |
|---------------------------|--------------------------|--------------|
| Certificate Number : | 5-TAS-2020-12270975 | |
| Inspection Date : | 04-08-2020 | |
| Certificate Print Date : | 04-08-2020 | |
| Services : | Registration Test | |
| Vehicle Testing Partner : | Tasjeel | |
| Vehicle Testing Center : | Tasjeel Emirates Auction | |
| Total Time Taken : | 12 min 0 sec | |
| Appointment Ref Number : | -- | |
| Start Time : | 11:40 | End Time : |
| | | 11:52 |
| Lane : | 01 | Token No. : |
| | | 6 |
| Attempt : | 1 | Prints No. : |
| | | 1 |

Carbon footprint



ton CO2



Keep protecting Dubai environment

Estimated Vehicle Consumption (Rate last 12 Months)

| | | | |
|-------------------|------------------------|--------------------|---------------------------|
| 24496 KM | 2521 L | 4085 AED | 6.1 ton |
| Distance per year | Fuel consumed per year | Fuel cost per year | Carbon footprint per year |

Parameter Readings

| | | | |
|--|---|--|--|
| Service brake imbalance on front axle 4 % | Service brake imbalance on rear axle 1 % | Parking brake imbalance between LHS and RHS 4 % | Vehicle on Petrol CO Reading 0.07 % |
|--|---|--|--|

Vehicle on Petrol HC Reading
25 PPM VOL

Inspection Remarks:

FRONT RIGHT SIDE CHASSIS ,WHEEL HOUSING REPAIRED, PASSED AS PER C.C.M W/O 20190119006,VIN FRAME REPAIRED PASSED AS PER PREVIOUS COMPANY LETTER.FRONT BULK HEAD,FENDER FRAME,BUMPER FRAME REPAIRED.

Payment Details

| | | | |
|----------------------------------|--------------------------------------|--------------------------------|---|
| Inspection Performed by 59460 | Payment Method VTP Credit Account | Transaction Number 12270975 | Service Fees AED 170 Collected on 04/08/2020 |
| Parking Slot No -- | Service Name Registration Test | Attempt 1 | Received by Raul Canceran Galang |

1 This is to acknowledge the receipt of AED 170 (in words: One Hundred and Seventy Dirhams Only.), towards the above service.

1 Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations.

هذه الشهادة صالحة لإجراء معاملة واحدة فقط خلال 30 يوم من تاريخ الفحص. المؤسسة غير مسؤولة عن العيوب الغير مرئية و الفحص الفني يتم ظاهريا طبقا لقانون السير و المرور لسنة 1995

