

Queue Number 2837362

Transaction Date 05 Oct 2026, 17:05:56

Site Name
840 - Emirates AuctionsTransaction Number
90122530 (CC10013) (CC10025)

Vehicle Details

Chassis Number 1N4AA51E2A*****
 Specification GCC Specification
 Make Nissan
 Model Maxima
 Model Year 2010
 Color White
 Mileage 209739 Km
 Fuel Type Petrol
 Transmission Type
 No. Of Cylinders 6

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Fenders	REPAINTED PORTION REPAIRED	مدكار
01.B Paint	BODY PORTION REPAINTED PORTION REPAIRED MINOR DENT SCRATCHES , PORTION GETTING FADED	الصبغ
01.C Doors	RIGHT SIDE BOTH REPAINTED PORTION REPAIRED , REAR LEFT SIDE PORTION REPAINTED	أبواب
01.D Rusty	UNDER FLOOR SUSPENSION PARTS GETTING RUSTY	صدأ
01.E Floor	UNDER FLOOR OILY PORTION MINOR DENT	الارضية
01.F Bumper	MISALIGN , PORTION LOOSE , HOOK COVER MISSING	دعامية
01.G Bonnet	REFITTED	غطاء المحرك
01.H Trunk	SHOCK NOT WORKING , MISALIGN	صندوق

02 Chassis Condition

الشاسي

02.A Chassis	CHASSIS CHECK VISIBLE AREA ONLY / OK	الشاسيه
--------------	--------------------------------------	---------

03 Engine Condition

المحرك

03.A Engine Visual Condition	OIL LEAK DRIPPING , REFITTED , PARTS GETTING RUSTY	الحالة النظرية للمحرك
------------------------------	--	-----------------------

04 Seats Condition

المقاعد

04.A Seat Condition	BACK DAMAGED , SIDE COVER LOOSE , BOTH SIDE ADJUSTMENT PORTION MISSING , RIGHT SIDE ADJUSTMENT NOT WORKING PROPERLY	حالة المقاعد
---------------------	---	--------------

05 Transmission Condition

الجير

Condition	Remarks	الحالة
05.A Gear Box Visual Condition	OIL LEAK , REFITTED , DELAY SHIFTING , JERKING , PARTS GETTING RUSTY	الحالة النظرية للجير
05.B Road Test	NOT CHECKED	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2023	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2023	الاطار الخلفي
06.C Rims Condition	MINOR DENT SCRATCHES	حالة الجنوط
07 Lights		الاضاءة
07.A Warning Light	WARNING LIGHT ON DISPLAY	ضوء تحذير
07.B Fog light	LEFT SIDE NOT WORKING	كشاف الضباب
08 Interior Condition		الحالة الداخليه
08.A Other	CENTER CONSOLE BOX PORTION LOOSE , INTERIOR PARTS GETTING RUSTY (SIGN OF FLOODED)	اخرى
08.B Mirror	LEFT SIDE COVER PORTION CRACK	المرآيا
08.C AC Condition	OK	المكيف
08.D Power Window Switch And Glass	REAR RIGHT SIDE SWITCH MAIN NOT WORKING	مفتاح النافذه و الزجاج
08.E Audio	SCREEN FADED	صوتيات
08.F Dash Board	CRACK , PORTION MELTED	لوحة القيادة
08.G Roof Ceiling	PORTION LOOSE	بطانه السقف
08.H Sun Visor	BOTH SIDE MIRROR LIGHT NOT WORKING	حاجب الشمس
08.I Door Panel	WORN OUT	لوحة بطانة الباب
08.J Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
08.K Gear Shifting Lever	SHIFTING LOCK RUBBER MISSING / KNOB WORN OUT	ذراع نقل السرعات
09 Engine Cooling System		نظام تبريد المحرك
09.A Coolant tank	BOTTLE CAP MODIFIED / WATER EMPTY	خزان التبريد

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

For complaints and inquiries reach out to us on
wecare@carscheck.ae

للشكاوي والمقترحات يمكنك التواصل معنا عبر
wecare@carscheck.ae