



Test Certificate

Site Number	: 840-EMIRATES AUCTION	Plate Code	: 0
Transaction Number	: 26899731	Plate Category	: PRIVATE
Transaction Date	: 08 JUN 2021 16:27:11	Plate Number	: 001036 EA
Queue Number	: 347214	Import Doc. Ref.	:
Chassis Number	: RKLBB9HE7E5001036	Manufacturer/Model	: TOYOTA/COROLLA
Engine Number	:	Model Year	: 2014
Vehicle Class	: LIGHT VEHICLE	Vehicle Color	: WHITE
Service / Indicator	: DSC AUCTION		

Statement of Vehicle Condition

Defect	Result	Remarks
VISUAL TEST:		
01 Lights		الانوار
01.04 - Head Lights	BOTH SIDE FADED	الانوار الامامية
02 Steering And Suspension System		عجلة القيادة ونظام التوصيلات
02.13 - Stub Axle Assemblies, Boots	RIGHT INNER AXLE BOOT CRACK	المحور
04 Tires Rims		الاطارات والعجلات
04.01 - Front Left And Right Hands Tires	TIRES 2018 /2019	الاطارات الامامية
05 Body		الهيكل
05.02 - Paint	BODY SCRATCH & DENT	الصنع
05.07 - Floor	TRUNK LID NOT CLOSING /MIDDLE FLOORING DENT	الارضية
06 General Items		الاشياء العامة
06.01 - Wiper Blades	WIPER BLADES WORN OUT	ماسحات الزجاج الامامي
06.08 - Interior Lights	INTERIOR ELECTRONIC NOT CHECK	الانوار الداخلية
06.12 - Seats Condition And Seats Fixing	INTERIOR PARTLY WORN OUT	المقاعد وحالتها وتثبيتها
06.16 - Engine Condition, Smoke	ENGINE & GEAR NOT CHECK (CAR NOT STARTING)	حالة المحرك - الدخان
06.21 - Battery Condition	BATTERY DEAD	حالة البطارية
07 Remarks		ملاحظات
07.04 - Others	149821 KM / BONNET LATCH DAMAGE	ملاحظات اخرى
09 Auction		الفحص الكامل
09.06 - Chassis Ok	OK	النشاصي جيد
09.10 - Engine Oil Leaking	MINOR OIL LEAK	تهريب زيت المحرك
09.25 - Body Repainted	BODY PORTIONS REPAINTED	اثر صنع في المركبة

The Test Certificate Shows the test Result at the time of inspection only.
Tasjeel is not responsible for any hidden defects.

شهادة الفحص تظهر نتيجة الفحص وقت الفحص فقط
تسجيل غير مسؤولة عن العيوب الخفية