

Queue Number	2672860	Transaction Date	24 Aug 2026, 10:03:42
Site Name	840 - Emirates Auctions	Transaction Number	10519303 (CC10008) (CC10011)



Vehicle Details

Chassis Number	SALGA2DF0F*****
Specification	GCC Specification
Make	Range Rover
Model	HSE
Model Year	2015
Color	White
Mileage	45940 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	8

Condition	Remarks	الحالة
01 Body		
01.A Paint	BODY PORTION REPAINTED,MINOR DENTS SCRATCHES	الصبغ
01.B Rusty	UNDER BODY PARTS ,POWER TRAIN GETTING RUSTY	صدأ
01.C Bumper	MINOR MISALIGN SCRATCHES	دعامية
01.D Roof	PORTION REPAINTED	السقف
01.E Bonnet	STAY SHOCK NOT WORKING	غطاء المحرك
01.F Trunk	SWITCH MELTED	صندوق
02 Chassis Condition		
02.A Chassis	CHASSIS COVERED VISIBLE AREA CHECKED / OK	الشاسيه
03 Engine Condition		
03.A Engine Visual Condition	PARTS GETTING RUSTY	الحالة النظرية للمحرك
04 Transmission Condition		
04.A Gear Box Visual Condition	PARTS GETTING RUSTY ,MINOR OIL LEAK	الحالة النظرية للجير
04.B Road Test	NOT CHECK	فحص علي الطريق
05 Tires and Rims Condition		
05.A Front Tyre	BOTH SIDE 2020 CRACK EXPIRED	الاطار الامامي
05.B Rear Tyre	BOTH SIDE 2020 CRACK EXPIRED	الاطار الخلفي

Condition	Remarks	الحالة
05.C Rims Condition	MINOR SCRATCHES	حالة الجنوط
06 Brake Condition		الفرامل
06.A Disc&Drum	GETTING RUSTY	دسك وطناير الفرامل
07 Suspension System		ممتص الصدمات
07.A Arms	BUSHES CHRACK	ازرع
08 Steering Condition		المقود
08.A Tie Rod End	BOOT CUT	مؤخرة الرودادات
09 Interior Condition		الحالة الداخلية
09.A AC Condition	OK	المكيف
09.B Roof Ceiling	LOOSE	بطانه السقف
09.C Sun Visor	FABRIC LOOSE	حاجب الشمس
09.D Engine Start Button	REMOTE PORTION WORN OUT	زر تشغيل المحرك

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

لشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae