CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2899752
Transaction Date	27 Oct 2026, 13:01:01
Site Name	840 - Emirates Auctions
Transaction Number	83226599 (CC10010) (CC10011)



Vehicle Details

Chassis Number	JTDBZ42E2A*******
Specification	GCC Specification
Make	Toyota
Model	Corolla
Model Year	2010
Color	Green
Mileage	516542 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition	Remarks	الحالة
01 Body		**جسم المركبة**
01.A Fenders	FRONT REFITTED	مدكار
01.B Paint	BODY PORTION REPAINTED,PORTION REPAIRED,MINOR DENTS SCRATCHES,PORTION FADED RUSTY	الصبغ
01.C Rusty	UNDER BODY SUSPENSION PARTS GETTING RUSTY.	صدأ
01.D Floor	UNDER FLOOR PORTION DENT ,MUDDY.,	الارضية
01.E Bumper	MISALIGN,PORTION DAMAGED	دعامية
01.F Bonnet	REFITTED	غطاء المحرك
01.G Trunk	MISALIGN REFITTED,STRIP DAMAGED	صندوق
01.H Sign of front accident	FRONT BUMPER FRAME , RADIATOR SUPPORT BULK HEAD,FENDER FRAME CROSS MEMBER REPAIRED.	وجود مؤشر لحادث في المقدمة
01.I Sign of back accident	BACK PANEL ,QUARTER PANEL COMPARTMENT FLOOR REPAIRED.	وجود مؤشر لحادث في الخلف
01.J Vehicle Color	GRAY	لون المركبة
02 Chassis Condition		**الشاصي**
02.A Chassis	FRONT CHASSIS END ,REAR BOTH SIDE CHASSIS EXTENSION REPAIRED DENT , GETTING RUSTY,	الشاسيه
03 Engine Condition		**المحرك**
03.A Smoke	BLACK	دخان
03.B Engine Visual Condition	REFITTED OIL LEAK,SHAKING ,ABNORMAL NOISY. PARTS RUSTY	الحالة النظريه للمحرك

Condition	Remarks	الحالة
04 Seats Condition		المقاعد
04.A Seat Condition	EXTRA COVER PORTION DAMAGED WORN OUT	حالة المقاعد
05 Transmission Condition		الجير
05.A Gear Box Visual Condition	REFITTED OIL LEAK ,JERKING ,COMPONENT PARTS RUSTY.	الحالة النظريه للجير
05.B Road Test	NOT CHECKED.	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2021 CRACK EXPIRED	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2023 CRACK,RIGHT SIDE PUNCTURE	الاطار الخلفي
07 Lights		الاضاءة
07.A Head Light	LENS FADED	الاضاءة الرئيسية
07.B Tail Light	RIGHT SIDE DAMAGED . .	الضوء الخلفي
07.C Warning Light	EXTRA WARNING LIGHT ON IN CLUSTER	ضوء تحذير
08 Brake Condition		الفرامل
08.A Brake Pedal	SPONGY.	دواسة الفرامل
08.B Disc&Drum	RUSTY .	دسك وطنابير الفرامل
09 Suspension System		ممتص الصدمات
09.A Shock Absorber	LEAK.	ممتص الصدمات
09.B Arms	LOWER ARM BUSHES CRACK	ازرع
10 Steering Condition		المقود
10.A Steering Boot	CUT .	ربلة المقود
10.B Steering Box	OIL LEAK ,HARD STEERING	جهاز المقود
11 Interior Condition		الحاله الداخليه
11.A Other	INTERIOR PARTS GETTING RUSTY ,SIGN OF FLOODED	اخري
11.B AC Condition	NO COOLING	المكيف
11.C Power Window Switch And Glass	FRONT LEFT SIDE NOT WORKING	مفتاح النافذه و الزجاج
11.D Dash Board	WORN OUT MELTED PORTION CRACK	لوحة القياده
11.E Roof Ceiling	REAR LEFT SIDE GRAB HANDLE MISSING,RIGHT SIDE LOOSE	بطانه السقف
11.F Sun Visor	LOOSE	حاجب الشمس
11.G Door Panel	PORTION WORN OUT	لوحة بطانة الباب
11.H Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
11.I Gear Shifting Lever	KNOB WORN OUT MELTED	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر **wecare@carscheck.ae**