



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	22 Jun 2022, 13:47:53
Transaction Number	49121402 (CC10008)	Queue Number	312309



Chassis Number	SALLSAA549A204826
Engine Number	
Vehicle Class	Car
Manufacturer	Range Rover
Model	Sport
Model Year	2009
Color	White
Mileage	241996 Km
Fuel Type	Petrol
No. Of Cylinders	8
Specification	GCC Specification

DEFECT	REMARKS	
01 Body		جسم المركبة
01.A Paint	BODY PORTION REPAIRED , REPAINTED & MINOR DENT ,SCRATCHES,PORTION RUSTY	الصبغ
01.B Floor	UNDER FLOOR COVERED & CHASSIS AREA MUDDY CHECKED VISIBLE AREA OK	الارضية
01.C Bonnet	SHOCK WEAK	غطاء المحرك
01.D Fenders	REAR LEFT SIDE PORTION REPAIRED,REPAINTED	مدكار
02 Transmission Condition		الجير
02.A Road Test	NOT CHECK	فحص علي الطريق
02.B Visual Gear Box Condition	MINOR OIL LEAK REFITTED	حالة الجير النظري
02.C Gear Box Mount	MOUNT RUBBER CRACKED	كرسي الجير
03 Tires and Rims Condition		الاطارات
03.A Front Tyre	BOTH SIDE 2018 , CRACKED	الاطار الامامي
03.B Rear Tyre	BOTH SIDE 2017/2018 EXPIRED	الاطار الخلفي
03.C Rims Condition	RIMS HAVE MINOR DENT SCRATCHES	حالة الجنوط
04 Engine Condition		المحرك

DEFECT	REMARKS	
04.A Visual Engine Condition	MINOR OIL LEAK REFITTED , ABNORMALNOISY	حالة المحرك النظري
05 Steering Condition		المقود
05.A Tie Rod End	BOOT CUT	مؤخرة الرودادات
05.B Steering Boot	BOOT CUT	ربلة المقود
06 Chassis Condition		الشاصي
06.A Chassis	CHECKED VISIBLE AREA OK	الشاسيه
07 Lights		الاضاءة
07.A Fog light	LEFT SIDE NOT WORKING	كشاف الضباب
07.B Warning Light	WARNING LIGHT ON IN DISPLAY	ضوء تحذير
07.C Head Light	LENS FADED & RIGHT SIDE LOW BEAM NOT WORKING	الاضاءة الرئيسية
08 Interior Condition		الحاله الداخليه
08.A AC Condition	OK	المكيف
08.B Roof Ceiling	LOOSE	بطانه السقف
08.C Dash Board	CRACKED	لوحة القيادة
08.D Other	CENTER CUP CONSOLE BOX SLIDING COVER DAMAGED	اخرى
09 Suspension System		ممتص الصدمات
09.A Arms	LOWER ARM BUSHES CRACKED	ازرع
09.B Ball Joint	BOOT CUT	مفصل كروي
09.C Other	STABLIZER LINK BOOT CUT	اخرى

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.