



## TEST CERTIFICATE

Site Number	<b>840-Emirates Auctions</b>	Transaction Date	<b>23 Jan 2023, 12:07:27</b>
Transaction Number	<b>80905719 (CC10006)</b>	Queue Number	<b>657844</b>



Chassis Number	<b>WF0TD35L06VL04749</b>
Engine Number	
Vehicle Class	<b>Car</b>
Manufacturer	<b>Ford</b>
Model	<b>Focus</b>
Model Year	<b>2006</b>
Color	<b>Black</b>
Mileage	<b>001 Km</b>
Fuel Type	<b>Petrol</b>
No. Of Cylinders	<b>4</b>
Specification	<b>GCC Specification</b>

DEFECT	REMARKS	
<b>01 Interior Condition</b>		<b>الحاله الداخليه</b>
01.A Dash Board	PORTION DAMAGE .	لوحة القيادة
01.B Steering Wheel and control buttons	WORN OUT .	عجلة القيادة وازرار التحكم
01.C Other	GEAR KNOB WORN OUT .	اخرى
01.D Odometer reading	NOT CHECKED .	قراءة عداد المسافات
01.E AC Condition	NOT CHECKED .	المكيف
<b>02 Tires and Rims Condition</b>		<b>الاطارات</b>
02.A Rear Tyre	BOTH SIDE EXPIRED DAMAGED .	الاطار الخلفي
02.B Front Tyre	BOTH SIDE EXPIRED ,DAMAGED .	الاطار الامامي
<b>03 Chassis Condition</b>		<b>الشاسي</b>
03.A Chassis	CHECKED VISIBLE AREA OK.	الشاسيه
<b>04 Body</b>		<b>جسم المركبة</b>
04.A Trunk	NOT OPEN .	صندوق
04.B Paint	BODY PORTION REPAIRED ,REPAINTED .MINOR DENTS SCRATCHES ON BODY .PAINT FADED ,PORTION GETTING RUSTY .	الصبغ

DEFECT	REMARKS	
04.C Rusty	UNDER BODY SUSPENSION PARTS GETTING RUSTY .	صدأ
04.D Bonnet	NOT OPEN ,ENGINE COMPARTMENT NOT CHECKED.	غطاء المحرك
04.E Bumper	MISALIGN PORTION DAMAGE.	دعامية
<b>05 Suspension System</b>		<b>ممتص الصدمات</b>
05.A Arms	LOWER ARM BUSHES CRACKED .	ازرع
05.B Ball Joint	BOOT CUT.	مفصل كروي
05.C Shock Absorber	LEAK WEAK .	ممتص الصدمات
<b>06 Transmission Condition</b>		<b>الجير</b>
06.A Road Test	NOT CHECKED .	فحص علي الطريق
06.B Visual Gear Box Condition	REFITTED OIL LEAK .	حالة الجير النظرى
<b>07 Steering Condition</b>		<b>المقود</b>
07.A Steering Box	OIL LEAK .	جهاز المقود
07.B Axle	BOOT CUT .	اكسلات
07.C Tie Rod End	WORN OUT .	مؤخرة الروداد
<b>08 Seats Condition</b>		<b>المقاعد</b>
08.A Seat Condition	PORTION DAMAGE .	حالة المقاعد
<b>09 Lights</b>		<b>الاضاءة</b>
09.A Head Light	LENS FADED .ALL LIGHTS NOT CHECKED .	الاضاءة الرئيسية
<b>10 Engine Condition</b>		<b>المحرك</b>
10.A Visual Engine Condition	ENGINE NOT START ,ALL SYSTEM NOT CHECKED ,KEY MISSING,REFITTED OIL LEAK .	حالة المحرك النظرى

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.