

Queue Number 2800870

Transaction Date 25 Sep 2026, 14:56:19

Site Name
840 - Emirates AuctionsTransaction Number
70618074 (CC10013) (CC10013)

Vehicle Details

Chassis Number MROCX12G8E*****
 Specification GCC Specification
 Make Toyota
 Model Hilux
 Model Year 2014
 Color White
 Mileage 328502 Km
 Fuel Type Petrol
 Transmission Type
 No. Of Cylinders 4

Condition	Remarks	الحالة
-----------	---------	--------

01 Body	جسم المركبة
---------	-------------

01.A Paint	BODY PORTION REPAINTED PORTION REPAIRED MINOR DENT SCRATCHES PORTION GETTING FADED RUSTY	الصبغ
01.B Rusty	UNDER BODY PARTS, SUSPENTION GETTING RUSTY	صدأ
01.C Floor	UNDER FLOOR MUDDY, PORTION DENTS	الارضية
01.D Bumper	MISALIGN, PORTION DENT MODIFIED	دعامية
01.E Fuel Tank	DENT	خزان الوقود
01.F Sign of front accident	FRONT BUMPER FRAME , FENDER FRAME ,BULKHEAD ,RADIATOR SUPPORT REPAIRED	وجود مؤشر لحادث في المقدمة

02 Chassis Condition	الشاسي
----------------------	--------

02.A Chassis	FRONT RIGHT SIDE CHASSIS MOUNT BRACKET REPAIRED / PORTION RUSTY BULGE	الشاسيه
--------------	---	---------

03 Engine Condition	المحرك
---------------------	--------

03.A Engine Visual Condition	REFITTED , MISFIRING , SHAKING , PARTS GETTING RUSTY	الحالة النظرية للمحرك
------------------------------	--	-----------------------

04 Seats Condition	المقاعد
--------------------	---------

04.A Seat Condition	PORTION WORN OUT / REAR CABIN MODIFIED	حالة المقاعد
---------------------	--	--------------

05 Transmission Condition	الجير
---------------------------	-------

05.A Gear Box Visual Condition	REFITTED , OIL WET , PARTS GETTING RUSTY	الحالة النظرية للجير
05.B Road Test	NOT CHECKED	فحص علي الطريق

Condition	Remarks	الحالة
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	2022 DRY CRACK	الاطار الامامي
06.B Rear Tyre	2022 DRY CRACK	الاطار الخلفي
07 Lights		الاضاءة
07.A Head Light	LENS FADED	الاضاءة الرئيسية
08 Brake Condition		الفرامل
08.A Disc&Drum	RUSTY	دسك و طنابير الفرامل
09 Interior Condition		الحالة الداخلية
09.A Other	INTERIOR PARTS GETTING RUSTY	اخرى
09.B AC Condition	OK , GRILL PORTION WONR OUT	المكيف
09.C Dash Board	GETTING FADED PORTION WORN OUT	لوحة القيادة
09.D Door Panel	PORTION WORN OUT	لوحة بطانة الباب
09.E Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
09.F Gear Shifting Lever	KNOB WORN OUT	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

For complaints and inquiries reach out to us on wecare@carscheck.ae

لشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae