



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	25 Sep 2021, 17:44:07
Transaction Number	70205740 (CC10006)	Queue Number	312309



Chassis Number	1GCSKSE32AZ168284
Engine Number	
Vehicle Class	Heavy
Manufacturer	Chevrolet
Model	Silverado
Model Year	2010
Color	Black
Mileage	152910

DEFECT	REMARKS	
01 Body		جسم المركبة
01.A Fenders	REPAIRED & REPAINTED	مدكار
01.B Paint	BODY TOTALY PORTION REPAIRED , REPAINTED & DENTS ,SCRATCHES ON BODY	الصبغ
01.C Doors	PORTION REPAIRED & REPAINTED	أبواب
01.D Rusty	UNDER BODY PARTS ,FLOORING , CHASSIS, SUSPENTION GETTING RUSTY	صدأ
01.E Floor	UNDER FLOOR THICK RUST PROOFED	الارضية
01.F Bumper	REPAINTED	دعامية
01.G Roof	REPAINTED	السقف
01.H Bonnet	REPAIRED & REPAINTED	غطاء المحرك
01.I Other	FRONT FENDER FRAME, BUMPER FRAME , RADITOR SUPPORT , BULK HEAD & CROSSMEMBER REPAIRED OLD GETTING RUSTY	اخرى
02 Chassis Condition		الشاسي
02.A Chassis	CHASSIS FRAME COMPLETLY THICK RUST PROOFED	الشاسيه
03 Seats Condition		المقاعد
03.A Other	OK	اخرى
04 Engine Condition		المحرك
04.A Other	OIL LEAK	اخرى
04.B Mount	BUSHES CRACKED	كرسي

DEFECT	REMARKS	
05 Exhaust System		نظام العادم
05.A Modification	MODIFIED & NOISY	تعديلات
05.B Other	WELDED & REPAIRED	اخرى
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2019	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2019	الاطار الخلفي
07 Wipers and Arms		المساحات
07.A Other	WORN OUT	اخرى
08 Lights		الاضاءة
08.A Head Light	OK	الاضاءة الرئيسية
08.B Other	OK	اخرى
08.C Indicator	REAR RIGHT SIDE NOT WORKING	الاشارات
09 Brake Condition		الفرامل
09.A Caliber Brake	RUSTY & WEAK	جهاز الفرامل
10 Suspension System		ممتص الصدمات
10.A Suspension Subframe	SUB FRAME & CROSS MEMBER GETTING RUSTY	
10.B Arms	FRONT BOTH SIDE LOWER ARMS & REAR CONTROL ARMS BUSHES CRACKED, RUSTY	ازرع
10.C Leaf Spring	BOTH SIDE BUSHES CRACKED & LEAF GETTING RUSTY	
10.D Shock Absorber	WEAK & RUSTY	ممتص الصدمات
11 Steering Condition		المقود
11.A Axle	BOOT LEAKING	اكسلات
11.B Other	STABILIZER LINK & CONTROL BAR BUSHES DRY CRACKED	اخرى
12 Interior Condition		الاجزاء الداخلية
12.A Other	OK	اخرى
12.B Mirror	OK	المرآيا
12.C AC Condition	OK	المكيف

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

