

Queue Number

2761243

Transaction Date

17 Sep 2026, 11:54:42

Site Name

840 - Emirates Auctions

Transaction Number

50832523 (CC10008) (CC10008)



Vehicle Details

Chassis Number	SALKA9B73P*****
Specification	GCC Specification
Make	Range Rover
Model	HSE
Model Year	2023
Color	White
Mileage	78288 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	8

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Fenders	FRONT RIGHT SIDE REPAINTED PORTION REPAIRED ,REFITTED MISALIGN	مدكار
01.B Paint	BODY PORTION REPAINTED PORTION REPAIRED ,BODY HAVE PROTECTION STICKER PAINT NOT CHECKED PROPERLY	الصبغ
01.C Doors	FRONT RIGHT SIDE REPAINTED PORTION REPAIRED ,REFITTED MISALIGN	أبواب
01.D Floor	UNDER BODY FLOOR ,CHASSIS ENGINE ,GEAR FULLY COVERED CHECKED VISIBLE AREA ONLY	الارضية
01.E Bonnet	REPAINTED PORTION REPAIRED ,REFITTED	غطاء المحرك
01.F Sign of front accident		وجود مؤشر لحادث في المقدمة
01.G Sign of side accident		وجود مؤشر لحادث في الجانب

02 Chassis Condition

الشاسي

02.A Chassis	FRONT RIGHT SIDE CHASSIS OUTER DENT	الشاسيه
02.B Other	FOR PROPERLY INSPECTION NEED TO REMOVE FENDER COVER UNDER COVER	اخرى

03 Engine Condition

المحرك

03.A Engine Visual Condition	OIL WET	الحالة النظرية للمحرك
------------------------------	---------	-----------------------

04 Transmission Condition

الجير

04.A Gear Box Visual Condition	MINOR JERKING	الحالة النظرية للجير
04.B Road Test	NOT CHECK	فحص علي الطريق

Condition	Remarks	الحالة
05 Tires and Rims Condition		الاطارات
05.A Front Tyre	BOTH SIDE 2025 CRACKED WORN OUT	الاطار الامامي
05.B Rear Tyre	BOTH SIDE 2025 GETTING WORN OUT	الاطار الخلفي
05.C Rims Condition	FRONT RIGHT SIDE RIM BEND	حالة الجنوط
06 Brake Condition		الفرامل
06.A Disc&Drum	GETTING RUSTY	دسك و طنابير الفرامل
07 Suspension System		ممتص الصدمات
07.A Arms	FRONT LOWER ARM CONTROL ARM DEEP SCRATCHES	ازرع
08 Steering Condition		المقود
08.A Axle	FRONT RIGHT SIDE CV AXLE DAMAGED, LOOSE, NOISY	اكسلات
09 Interior Condition		الحالة الداخلية
09.A AC Condition	OK	المكيف
09.B Floor Matting	PORTION DIRTY	فرش الأرضية

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

For complaints and inquiries reach out to us on wecare@carscheck.ae

للشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae