



## TEST CERTIFICATE

Site Number	<b>840-Emirates Auctions</b>	Transaction Date	<b>10 May 2022, 16:50:41</b>
Transaction Number	<b>75307939 (CC10006)</b>	Queue Number	<b>312309</b>



Chassis Number	<b>WPOZZZ98Z2U641689</b>
Engine Number	
Vehicle Class	<b>Car</b>
Manufacturer	<b>Porsche</b>
Model	<b>Boxster</b>
Model Year	<b>2002</b>
Color	<b>Black</b>
Mileage	<b>140771 Km</b>
Fuel Type	<b>Petrol</b>
No. Of Cylinders	<b>6</b>
Specification	<b>GCC Specification</b>

DEFECT	REMARKS	
<b>01 Interior Condition</b>		<b>الحاله الداخليه</b>
01.A Roof Ceiling	LOOSE	بطانه السقف
01.B Sunroof	ROOF CONVERTABLE NOT WORKING	فتحت سقف
01.C AC Condition	OK	المكيف
01.D Sun Visor	BOTH SIDE MIRROR COVER MISSING	حاجب الشمس
<b>02 Tires and Rims Condition</b>		<b>الاطارات</b>
02.A Front Tyre	BOTH SIDE 2021	الاطار الامامي
02.B Rear Tyre	BOTH SIDE 2021	الاطار الخلفي
<b>03 Body</b>		<b>جسم المركبة</b>
03.A Fenders	FRONT LEFT SIDE REPAINTED & REAR LEFT SIDE PORTION REPAIRED,REPAINTED	مدكار
03.B Paint	BODY PORTION REPAIRED, REPAINTED,MINOR DENT,SCRATCHES	الصيغ
03.C Doors	LEFT SIDE REPAINTED	أبواب
03.D Floor	UNDER BODY COVERED	الارضية
03.E Bonnet	PORTION REPAIRED,REPAINTED & STAND MISSING	غطاء المحرك
03.F Trunk	REPAINTED	صندوق

DEFECT	REMARKS	
03.G Roof	REPAIRED,REPAINTED	السقف
<b>04 Transmission Condition</b>		<b>الجير</b>
04.A DIFFERENTIAL	SIGN OF LEAK	الدفرنشيل
04.B Road Test	NOT CHECK	فحص علي الطريق
04.C Visual Gear Box Condition	OK	حالة الجير النظرى
<b>05 Engine Condition</b>		<b>المحرك</b>
05.A Visual Engine Condition	REFITTED	حالة المحرك النظرى
<b>06 Lights</b>		<b>الاضاءة</b>
06.A Other	LIGHT SWITCH NOT WORKING PROPERLY	اخرى
<b>07 Chassis Condition</b>		<b>الشاسي</b>
07.A Chassis	CHECKED VISIBLE AREA OK	الشاسيه

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.