

Queue Number 2870340

Transaction Date 16 Oct 2026, 12:27:29

Site Name
840 - Emirates AuctionsTransaction Number
74491895 (CC10013) (CC10011)

Vehicle Details

Chassis Number	WBAKR6104E*****
Specification	GCC Specification
Make	BMW
Model	X5
Model Year	2014
Color	Brown
Mileage	143308 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	8

Condition	Remarks	الحالة
-----------	---------	--------

01 Body جسم المركبة

01.A Fenders	FRONT BOTH SIDE FIBER PAINT NOT CHECK,REAR RIGHT REPAINTED PORTION REPAIRED	مدكار
01.B Paint	BODY PORTION REPAINTED,PORTION REPAIRED,MINOR DENT SCRATCHES	الصبغ
01.C Doors	FRONT RIGHT SIDE,REAR BOTH SIDE REPAINTED PORTION REPAIRED	أبواب
01.D Rusty	UNDER FLOOR SUSPENSION PARTS GETTING RUSTY	صدأ
01.E Floor	UNDER FLOOR COVERED FOR FULL INSPECTION REMOVE INNER FENDER UNDER ENGINE FLOOR COVER FOR RECHECK	الارضية
01.F Bumper	MISALIGN	دعامية
01.G Trunk	PORTION REPAINTED	صندوق

02 Chassis Condition الشاسي

02.A Chassis	CHASSIS COVERED MUDDY CHECK VISIBLE AREA ONLY / OK	الشاسيه
--------------	--	---------

03 Engine Condition المحرك

03.A Engine Visual Condition	MINOR OIL LEAK , REFITTED , PARTS GETTING RUSTY	الحالة النظرية للمحرك
------------------------------	---	-----------------------

04 Seats Condition المقاعد

04.A Seat Condition	FRONT BOTH SEAT SIDE COVER LOOSE,RIGHT SIDE PORTION DAMAGED WORN OUT	حالة المقاعد
---------------------	--	--------------

05 Transmission Condition الجير

05.A Gear Box Visual Condition	MINOR JERKING , REFITTED , PARTS GETTING RUSTY	الحالة النظرية للجير
--------------------------------	--	----------------------

Condition	Remarks	الحالة
05.B Propeller Shaft	FLANGE RUBBER CRACKED	ناقل الحركة
05.C Road Test	NOT CHECKED	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2024	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2024	الاطار الخلفي
06.C Rims Condition	DENTS SCRATCHES	حالة الجنوط
07 Wipers and Arms		المساحات
07.A Other	BOTTLE CAP MISSING	اخرى
08 Lights		الاضاءة
08.A Head Light	LENS GETTING FADED	الاضاءة الرئيسية
09 Brake Condition		الفرامل
09.A Hand Brake	SWITCH CRACKED	فرامل اليد
10 Suspension System		ممتص الصدمات
10.A Arms	ARM BUSHES CRACKED	ازرع
11 Steering Condition		المقود
11.A Tie Rod End	BOOT CUT	مؤخرة الرودادات
11.B Axle	BOOT LEAK	اكسلات
12 Interior Condition		الحالة الداخليه
12.A Other	CENTER CONSOLE BOX COVER WORN OUT,CUP HOLDER SLIDING COVER DAMAGED,INTERIOR PARTS GETTING RUSTY	اخرى
12.B Mirror	LEFT SIDE GETTING FADED	المرآيا
12.C AC Condition	OK	المكيف
12.D Power Window Switch And Glass	BOTH SIDE CURTAIN HANDLE DAMAGED	مفتاح النافذه و الزجاج
12.E Roof Ceiling	LOOSE	بطانه السقف
12.F Sun Visor	RIGHT SIDE MINOR LOOSE	حاجب الشمس
12.G Door Panel	PORTION DAMAGED LOOSE	لوحة بطانة الباب
12.H Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة،
كما لا تضمن بموجب هذه الشهادة صلاحية المركبة
للتسجيل من عدمه

للسكاوي والمقترحات يمكنك التواصل معنا عبر
wecare@carscheck.ae