

Queue Number 2384707

Transaction Date 11 May 2026, 17:40:49

Site Name
840 - Emirates AuctionsTransaction Number
98313927 (CC10013) (CC10011)

Vehicle Details

Chassis Number	JN8AY2NYXH*****
Specification	GCC Specification
Make	Nissan
Model	Patrol
Model Year	2017
Color	White
Mileage	261622 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	8

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Fenders	FRONT BOTH SIDE REPAINTED PORTION REPAIRED , REFITTED	مدكار
01.B Paint	BODY PORTION REPAINTED,PORTION REPAIRED,MINOR DENT SCRATCHES,PORTION FADED RUSTY	الصبغ
01.C Doors	FRONT LEFT SIDE REPAINTED	أبواب
01.D Rusty	UNDER FLOOR SUSPENSION PARTS GETTING RUSTY	صدأ
01.E Floor	UNDER FLOOR MOUNT RUBBER DRY CRACK	الارضية
01.F Bumper	MISALIGN	دعامية
01.G Bonnet	REPAINTED PORTION REPAIRED , REFITTED , SHOCK WEAK	غطاء المحرك

02 Chassis Condition

الشاسي

02.A Chassis	CHASSIS FRAME GETTING RUSTY PORTION BULGED	الشاسيه
--------------	--	---------

03 Engine Condition

المحرك

03.A Engine Visual Condition	DIRTY , COMPONENTS REFITTED , PARTS GETTING RUSTY	الحالة النظرية للمحرك
------------------------------	---	-----------------------

04 Seats Condition

المقاعد

04.A Seat Condition	DRIVER SEAT LOOSE , RIGHT SIDE ADJUSTMENT NOT WOREKING PROPERLY	حالة المقاعد
---------------------	---	--------------

05 Transmission Condition

الجير

05.A Gear Box Visual Condition	MINOR JERKING , PARTS GETTING RUSTY	الحالة النظرية للجير
--------------------------------	-------------------------------------	----------------------

Condition	Remarks	الحالة
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2026	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2026	الاطار الخلفي
07 Brake Condition		الفرامل
07.A Disc&Drum	GETTING RUSTY	دسك و طنابير الفرامل
08 Suspension System		ممتص الصدمات
08.A Arms	ARM BUSHES DRY CRACK	ازرع
08.B Stabilizer Bar And Link Rod	BOOT CUT	عمود التوازن و مثبت عمود التوازن
09 Steering Condition		المقود
09.A Steering Oil	OIL LEAK	زيت المقود
09.B Steering Boot	BOOT CUT LEAK	ربلة المقود
10 Interior Condition		الحالة الداخلية
10.A Other	INTERIOR PARTS GETTING MINOR REFITTED	اخرى
10.B AC Condition	NOT COOLING	المكيف

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

للشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae