CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2934018
Transaction Date	03 Nov 2026, 12:49:53
Site Name	840 - Emirates Auctions
Transaction Number	60329912 (CC10010) (CC10010)



Vehicle Details

Chassis Number	JTFHX02P57*******
Specification	GCC Specification
Make	Toyota
Model	Hiace
Model Year	2007
Color	White
Mileage	348652 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Paint	BODY REPAINTED, PORTION REPAIRED DENTS, SCRATCHES , PORTION RUSTY, PORTION FADED	الصبغ
01.B Rusty	UNDER BODY SUSPENSION PARTS GETTING RUSTY.	صدأ
01.C Floor	FLOORING RUNNING BOARD SIDE PANEL REPAIRED ,DENT GETTING RUSTY.	الارضية
01.D Bumper	MISALIGN,SCRATCHES , LOOSE ,PORTION DAMAGED.	دعامية
01.E Pillars	FRONT DOOR PILLAR ROCKER PANEL REPAIRED	القوائم
01.F Sign of front accident	FRONT BUMPRER FRAME ,FIREWALL COWL PANEL DOOR POST WHEEL ARCH REPAIRED.	وجود مؤشر لحادث في المقدمة
01.G Sign of side accident	SIDE PANEL WHEEL ARCH INNER QUARTER PANEL REPAIRED.	وجود مؤشر لحادث في الجانب
01.H Sign of back accident	BACK PANEL ,QUARTER PANEL COMPARTMENT FLOOR REPAIRED.	وجود مؤشر لحادث في الخلف
02 Chassis Condition		الشاصي
02.A Chassis	FRONT BOTH SIDE CHASSIS UPPORT SKIRT BADLY REPAIRED BEND KINK . REAR EXTENSION END DENT .	الشاسيه
03 Engine Condition		المحرك
03.A Engine Visual Condition	ENGINE NOT START ,ALL SYSTEM NOT CHECKED ,REFITTED OIL LEAK,PARTS RUSTY	الحالة النظريه للمحرك
04 Seats Condition		المقاعد
04.A Seat Condition	DIRTY LOOSE PORTION CUT .	حالة المقاعد
05 Transmission Condition		الجير

Condition	Remarks	الحالة
05.A Gear Box Visual Condition	NOT CHECKED.	الحالة النظريه للجير
05.B Road Test	NOT CHECKED.	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2026.	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2026.	الاطار الخلفي
06.C Rims Condition	RUSTY,	حالة الجنوط
07 Lights		الاضاءة
07.A Head Light	LENS FADED, ALL LIGHTS NOT CHECK	الاضاءة الرئيسية
07.B Tail Light	PORTION CRACKED.	الضوء الخلفي
08 Brake Condition		الفرامل
08.A Disc&Drum	RUSTY.	دسك وطنابير الفرامل
09 Suspension System		ممتص الصدمات
09.A Shock Absorber	LEAK .	ممتص الصدمات
09.B Leaf Spring	BUSHES CRACKED.	
09.C Arms	BUSHES CUT .	ازرع
10 Steering Condition		المقود
10.A Steering Boot	CUT .	ربلة المقود
10.B Steering Box	OIL LEAK .	جهاز المقود
11 Interior Condition		الحاله الداخليه
11.A Other	INTERIOR PARTS GETTING RUSTY ,SIGN OF FLOODED.	اخري
11.B AC Condition	NOT CHECKED.	المكيف
11.C Dash Board	PORTION LOOSE.	لوحة القياده
11.D Roof Ceiling	LOOSE PORTION CUT .	بطانه السقف
11.E Door Panel	WORN OUT PORTION LOOSE.	لوحة بطانة الباب
11.F Steering Wheel and control buttons	WORN OUT.	عجلة القيادة وازرار التحكم
11.G Gear Shifting Lever	KNOB WORN OUT.	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة،
كما لا تضمن بموجب هذه الشهادة صلاحية المركبة
.للتسجيل من عدمه

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae