



Test Certificate

Site Number	: 840-EMIRATES AUCTION	Plate Code	: 0
Transaction Number	: 21019098	Plate Category	: PRIVATE
Transaction Date	: 09 SEP 2020 14:57:28	Plate Number	: 044 EA
Queue Number	: 218304	Import Doc. Ref.	:
Chassis Number	: WDDDJ72X78A133044	Manufacturer/Model	: MERCEDES/CLS 550
Engine Number	:	Model Year	: 2008
Vehicle Class	: LIGHT VEHICLE	Vehicle Color	: SILVER
Service / Indicator	: DSC AUCTION		

Statement of Vehicle Condition

Defect	Result	Remarks
AUTOMATIC TEST:		
13 Brake System		الفرامل
13.04 - Brake Test	Passed	فحص الفرامل
14 Exhaust Gas Test		الغاز العادم والكربون
14.01 - Exhaust Gas Test	Passed	فحص الغاز العادم-الكربون
VISUAL TEST:		
02 Steering And Suspension System		عجلة القيادة ونظام التوصيلات
02.13 - Stub Axle Assemblies, Boots		المحور
02.15 - Suspension Crack Or Bend, Bushes		التوصيلات
03 Brake System		نظام الفرامل
03.01 - Brake Efficiency Front Wheels Left And Right Hands		قوة فرامل المحور الامامي
04 Tires Rims		الاطارات والعجلات
04.01 - Front Left And Right Hands Tires		الاطارات الامامية
04.07 - Rims		الرنجات
05 Body		الهيكل
05.02 - Paint		الصبغ
05.03 - Doors		الابواب
05.04 - Fenders		المدكار
05.06 - Roof		السقف
05.08 - Chassis (Frame)		الشاصية
05.09 - Front And Rear Windshields		الزجاج الامامي والخلفي
05.12 - Side Safety Frame		الواقيات الجانبية
06 General Items		الاشياء العامة
06.10 - Mirrors Side View		المرآيا الجانبية
06.12 - Seats Condition And Seats Fixing		المقاعد وحالتها وتثبيتها
06.13 - Exhaust System		نظام العادم



Test Certificate

Site Number	: 840-EMIRATES AUCTION	Plate Code	: 0
Transaction Number	: 21019098	Plate Category	: PRIVATE
Transaction Date	: 09 SEP 2020 14:57:28	Plate Number	: 044 EA
Queue Number	: 218304	Import Doc. Ref.	:
Chassis Number	: WDDDJ72X78A133044	Manufacturer/Model	: MERCEDES/CLS 550
Engine Number	:	Model Year	: 2008
Vehicle Class	: LIGHT VEHICLE	Vehicle Color	: SILVER
Service / Indicator	: DSC AUCTION		

Statement of Vehicle Condition

06.14 - Transmission Condition	OK	حالة ناقل الحركة
06.16 - Engine Condition, Smoke	OK	حالة المحرك - الدخان
07 Remarks		ملاحظات
07.04 - Others	152226 KMS / OIL COOLER LINES LEAK / FRONT BUMPER REPAIRED	ملاحظات اخرى
09 Auction		الفحص الكامل
09.02 - Need Wheel Alignment		يحتاج الى ميزانية العجلات
09.14 - Sign Of Front Accident		أثر حادث في مقدمة المركبة
09.24 - Digital Display Damaged/Warning Lights	LICENSE PLATE LAMP FAULTY MESSAGE ON	عطل في لوحة التحكم الالكتروني
09.25 - Body Repainted	BODY PORTIONS REPAINTED	أثر صيغ في المركبة
<p>The Test Certificate Shows the test Result at the time of inspection only. Tasjeel is not responsible for any hidden defects.</p> <p>شهادة الفحص تظهر نتيجة الفحص وقت الفحص فقط تسجيل غير مسؤولة عن العيوب الخفية</p>		

Test Certificate



Vehicle
Registration



✓ PASS

Possession Certificate : 64569371

Chassis No : WDDJ72X78A133044

Vehicle Make : MERCEDES

Vehicle Model : CLS 550

Vehicle Class : Light Vehicle

Body Type : SALOON

Fuel : Benzene

Color : Silver

Drive Direction : Left Hand Side

Dimensions : (H x W x L) -- x -- x --

Current Odometer : 152228 Kms.

Origin : Germany

Model Year : 2008

Gear Type : Automatic

Engine Size : 4700 CC

Engine No : NO

Horse Power : 382

Axles No : 2

Cylinders : 8

No Of Doors : 4

No Of Seats : 5

G. V. W. :

2200 Kgs.

Empty Weight : 1823 Kgs.

Certificate Number : 5-TAS-2020-12579679

Inspection Date : 19-09-2020

Certificate Print Date : 19-09-2020

Services : Registration Test

Vehicle Testing Partner : Tasjeel

Vehicle Testing Center : Tasjeel Emirates Auction

Total Time Taken :
2 min 24 sec

Appointment Ref Number : --

Start Time : 15:42

End Time : 15:44

Lane : 01

Token No. : 5

Attempt : 2

Prints No : 1

Carbon footprint



Thank you! You are environment protector

Estimated Vehicle Consumption (Rate last 12 Months)



11213 KM

Distance per
year



1154 L

Fuel consumed
per year



1870 AED

Fuel cost per
year



2.8 ton

Carbon footprint
per year

Inspection Findings

Discrepancies

Incorrect information about GCC specific specifications with No Document

Old Value

Yes

New Value

No

Verified

Inspection Remarks: FRONT RIGHT SIDE MEMBER OUTER SKIRT REPAIRED/FRONT RIGHT FENDER BRACKET REPAIRED

Payment Details

Inspection Performed by

59460

Payment Method

VTP Credit Account

Transaction Number

12579679

Service Fees

AED 70 Collected on 19/09/2020

Parking Slot No

--

Service Name

Registration Test

Attempt

2

Received by

Raul Canceran Galang

1 This is to acknowledge the receipt of AED 70 (in words: Seventy Dirhams Only.), towards the above service.

1 Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations.

هذه الشهادة صالحة لإجراء معاملة واحدة فقط خلال 30 يوم من تاريخ الفحص. المؤسسة غير مسئولة عن العيوب الغير مرئية و الفحص الفني يتم ظاهريا طبقا لقانون السير و المرور 21 لسنة 1995

This certificate is valid for one transaction only for 30 days from the date of inspection. Company not responsible for any hidden defects and inspection done-According to Traffic law No., 21 year 1995

