

Queue Number 2827438

Transaction Date 02 Oct 2026, 16:55:49

Site Name
840 - Emirates AuctionsTransaction Number
53383534 (CC10013) (CC10011)

Vehicle Details

Chassis Number	LSJW54U9XL*****
Specification	GCC Specification
Make	MG
Model	6
Model Year	2020
Color	Red
Mileage	158364 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition	Remarks	الحالة
-----------	---------	--------

01 Body جسم المركبة

01.A Fenders	REAR LEFT SIDE DEEP DENTS	مدكار
01.B Paint	MINOR DENTS SCRATCHES ON BODY	الصبغ
01.C Rusty	UNDER FLOOR SUSPENSION PARTS GETTING RUSTY	صدأ
01.D Floor	UNDER FLOOR PORTION MINOR DENT	الارضية
01.E Bumper	MISALIGN	دعامية
01.F Trunk	NOT OPEN	صندوق

02 Chassis Condition الشاسي

02.A Chassis	CHASSIS CHECK VISIBLE AREA ONLY / OK	الشاسيه
--------------	--------------------------------------	---------

03 Engine Condition المحرك

03.A Engine Visual Condition	NOT STRAT ALL SYSTEM NOT CHECK , PARTS GETTING RUSTY	الحالة النظرية للمحرك
------------------------------	--	-----------------------

04 Transmission Condition الجير

04.A Gear Box Visual Condition	NOT CHECK , PARTS GETTING RUSTY	الحالة النظرية للجير
04.B Road Test	NOT CHECKED	فحص علي الطريق

05 Tires and Rims Condition الاطارات

05.A Front Tyre	2022 DRY CRACK	الاطار الامامي
05.B Rear Tyre	2021 EXPIRED CRACKED	الاطار الخلفي

Condition	Remarks	الحالة
06 Lights		الاضاءة
06.A Head Light	ALL LIGHT NOT CHECK	الاضاءة الرئيسية
07 Brake Condition		الفرامل
07.A Disc&Drum	GETTING RUSTY	دسك و طنابير الفرامل
08 Interior Condition		الحالة الداخليه
08.A Other	INTERIOR PARTS DIRTY MINOR GETTING RUSTY	اخرى
08.B AC Condition	NOT CHECKED	المكيف
08.C Dash Board	GETTING RUSTY	لوحة القيادة

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

For complaints and inquiries reach out to us on wecare@carscheck.ae

للشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae