CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2998616
Transaction Date	16 Nov 2026, 16:52:18
Site Name	840 - Emirates Auctions
Transaction Number	26864806 (CC10013) (CC10011)



Vehicle Details

Chassis Number	SCBCA13S4J*******
Specification	Imported
Make	Bentley
Model	Continental
Model Year	2019
Color	Black
Mileage	58182 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	12

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Fenders	REFITTED	مدكار
01.B Paint	BODY TOTALLY PROTECTION STICKER PAINT NOT CHECK	الصبغ
01.C Rusty	UNDERE FLOOR SUSPENSION PARTS GETTING RUSTY	صدأ
01.D Floor	UNDER FLOOR COMPLETELY COVERED DIRTY MUDDY / UNDER ENGIEN & REAR UNDER COMPARTMENT COVER MISSING	الارضية
01.E Bumper	MISALIGN	دعامية
01.F Windshield	REAR CRACKED	زجاج
01.G Bonnet	REFITTED,STAY SHOCK NOT WORKING	غطاء المحرك
01.H Trunk	REAR OUTER SWITCH , SPOILER NOT WORKING , REFITTED	صندوق
01.I Vehicle Year Model	2018	سنة صنع المركبة
02 Chassis Condition		الشاصي
02.A Chassis	CHASSIS COVERED DIRTY CHECK VISIBLE AREA ONLY / OK	الشاسيه
02.B Other	FOR FULL INSPECTION MAKE STEAM WASH & REMOVE ALL INNER FENDER UNDER FLOOR COVER FOR RECHECK	اخري
03 Engine Condition		المحرك
03.A Other	UPPER COVER PART MISSING	اخري
03.B Engine Visual Condition	COMPONENTS REFITTED, PARTS GETTING RUSTY	الحالة النظريه للمحرك
04 Transmission Condition		الجير

Condition	Remarks	الحالة
04.A Gear Box Visual Condition	PARTS GETTING RUSTY	الحالة النظريه للجير
04.B Road Test	NOT CHECKED	فحص علي الطريق
05 Tires and Rims Condition		الاطارات
05.A Front Tyre	BOTH SIDE 2023 DRY CRACK	الاطار الامامي
05.B Rear Tyre	LEFT SIDE 2022 CRACK,RIGHT 2021 CRACKED EXPIRED	الاطار الخلفي
06 Lights		الاضاءة
06.A Warning Light	WARNING MESSAGE ON DISPLAY	ضوء تحذير
07 Suspension System		ممتص الصدمات
07.A Shock Absorber	RIGHT SIDE SHOCK PORTION DENT	ممتص الصدمات
07.B Arms	ARM BUSHES DRY CRACK	ازرع
07.C Ball Joint	BOOT DRY CRACK	مفصل كروي
08 Interior Condition		الحاله الداخليه
08.A Other	REAR CONSOLE BOX SIDE PANEL PORTION MISALIGN / INTERIOR PARTS MINOR GETTING RUSTY	اخري
08.B AC Condition	OK	المكيف
08.C Dash Board	LEATHER PORTION LOOSE	لوحة القياده
08.D Sun Visor	RIGHT SIDE MIRROR DAMAGED	حاجب الشمس

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae