

## **TEST CERTIFICATE**

Site Number
Transaction Number

Condition

840-Emirates Auctions 98259462 (CC10006) Transaction Date

09 Aug 2022, 14:49:42

Queue Number 312309

Chassis Number

WDCED6EB3JA089818

Engine Number

Vehicle Class Car

Manufacturer Mercedes

Model GLE 43

Model Year 2018

Color White

Mileage 28347 Km

Fuel Type Petrol

No. Of Cylinders

Specification

**GCC Specification** 

الارضية

DEFECT REMARKS

O1 Lights

O1.A Warning Light WARNING LIGHT ON DISPLAY

ضوء تحذير

 02 Body

O2.A Paint BODY PORTION REPAIRED , REPAINTED & MINOR DENT الصبغ

,SCRATCHES

02.B Floor UNDER FLOOR FENDER CHASSIS FULLY COVERED

CHECKED VISIBLE AREA

 03 Transmission Condition

O3.A Road TestNOT CHECKفحص علي الطريقO3.B Visual Gear BoxOKحالة الجير النظري

 04 Tires and Rims Condition

O4.A Front TyreBOTH SIDE 2019O4.B Rear TyreBOTH SIDE 2019O4.C Rims ConditionRIMS HAVE MINOR DENT SCRATCHES

O5 Interior Condition الحاله الداخلية

O5.A AC Condition OK

DEFECT	REMARKS	
06 Chassis Condition		الشاصي
06.A Chassis	CHECKED VISIBLE AREA OK	الشاسيه
07 Engine Condition		المحرك
07.A Visual Engine Condition	ОК	حالة المحرك النظرى

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate,
   Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.