



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	31 Oct 2022, 12:21:57
Transaction Number	13318335 (CC10006)	Queue Number	614121



Chassis Number	WDDZF4JB2HA023823
Engine Number	
Vehicle Class	Car
Manufacturer	Mercedes
Model	E 300
Model Year	2017
Color	Silver
Mileage	123110 Km
Fuel Type	Petrol
No. Of Cylinders	4
Specification	USA Imported

DEFECT	REMARKS	
01 Interior Condition		الحاله الداخليه
01.A AC Condition	OK	المكيف
01.B Dash Board	REXIN LOOSE.	لوحة القيادة
01.C Sun Visor	LEFT SIDE COVER MIRROR MISSING	حاجب الشمس
02 Body		جسم المركبة
02.A Doors	FRONT BOTH SIDE PORTION REPAIRED, REPAINTED	أبواب
02.B Sign of front accident		وجود مؤشر لحادث في المقدمة
02.C Other	FRONT BUMPER FRAME ,FENDER FRAME ,BULKHEAD RPAIRED.	اخرى
02.D Floor	UNDER FLOOR COVERED,CHECKED ONLY VISIBLE AREA.LEFT SIDE COVER DAMAGED.RIGHT SIDE COVER MISSING .	الارضيه
02.E Bonnet	SHOCK WEAK & REPAINTED , REFITTED	غطاء المحرك
02.F Fenders	FRONT BOTH SIDE REPAIRED, REPAINTED & REFITTED	مدكار
02.G Paint	BODY PORTION REPAIRED , REPAINTED & MINOR DENT ,SCRATCHES,	الصبغ
02.H Bumper	MISALIGN.	دعامية
03 Tires and Rims Condition		الاطارات

DEFECT	REMARKS	
03.A Rear Tyre	BOTH SIDE 2020	الاطار الخلفي
03.B Front Tyre	BOTH SIDE 2020	الاطار الامامي
04 Suspension System		ممتص الصدمات
04.A Arms	LOWER ARM BUSHES CUT.	ازرع
05 Engine Condition		المحرك
05.A Visual Engine Condition	REFITTED.	حالة المحرك النظري
06 Engine Cooling System		نظام تبريد المحرك
06.A Coolant tank	WARNING MESSAGE ON COOLANT LEVEL LOW.	خزان التبريد
06.B Radiator Condition	COOLANT LEAKING.	حالة المبرد
07 Chassis Condition		الشاسي
07.A Chassis	CHECKED VISIBLE AREA OK.	الشاسيه
08 Transmission Condition		الجير
08.A Road Test	NOT CHECK	فحص علي الطريق
08.B Visual Gear Box Condition	JERKING,REFITTED.	حالة الجير النظري
09 Seats Condition		المقاعد
09.A Seat Condition	LEFT PORTION DAMAGE.	حالة المقاعد

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.