



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	15 Mar 2023, 12:24:10
Transaction Number	40711170 (CC10009)	Queue Number	687989



Chassis Number	SALLSAAE4DA768957
Engine Number	
Vehicle Class	Car
Manufacturer	Range Rover
Model	Sport
Model Year	2013
Color	White
Mileage	122645 Km
Fuel Type	Petrol
No. Of Cylinders	8
Specification	GCC Specification

DEFECT	REMARKS	
01 Interior Condition		الحاله الداخليه
01.A Roof Ceiling	PORTION LOOSE	بطانه السقف
01.B Roof Light	PORTION LOOSE	أنارة السقف
01.C Dash Board	CONSOLE BOX LOCK DAMAGED	لوحة القيادة
01.D AC Condition	OK	المكيف
02 Transmission Condition		الجير
02.A Road Test	NOT CHECK	فحص علي الطريق
02.B Visual Gear Box Condition	OIL LEAK,JERKING, REFITTED . GEAR BOX FAULT WARNING MESSAGE SHOWING IN DISPLAY	حالة الجير النظري
02.C DIFFERENTIAL	MINOR OIL LEAK	الدفرنشل
02.D Gear Box Mount	MOUNT CRACK	كرسي الجير
03 Lights		الاضاءة
03.A Warning Light	WARNING MESSAGE & WARNING LIGHT ON IN DISPLAY	ضوء تحذير
04 Engine Condition		المحرك
04.A Mount	MOUNT CRACK	كرسي
04.B Visual Engine Condition	OIL LEAK REFITTED, SIGN OF OVER HEAT	حالة المحرك النظري
04.C Smoke	WHITE	دخان

DEFECT	REMARKS	
05 Body		جسم المركبة
05.A Fenders	REPAINTED PORTION REPAIRED	مدكار
05.B Doors	FRONT LEFT SIDE REPAINTED	أبواب
05.C Bonnet	REFITTED	غطاء المحرك
05.D Paint	BODY PORTION REPAINTED PORTION REPAIRED & MINOR DENT ,SCRATCHES	الصبغ
06 Brake Condition		الفرامل
06.A Brake Pedal	SPONGY	دواسة الفرامل
06.B Hand Brake	NOT WORKING	فرامل اليد
07 Tires and Rims Condition		الاطارات
07.A Front Tyre	BOTH SIDE 2020	الاطار الامامي
07.B Rims Condition	MINOR SCRATCHES	حالة الجنوط
07.C Rear Tyre	BOTH SIDE 2020	الاطار الخلفي
08 Steering Condition		المقود
08.A Tie Rod End	BOOT CUT	مؤخرة الرودادات
08.B Axle	BOOT CUT	اكسلات
08.C Steering Oil	MINOR OIL LEAK	زيت المقود
09 Chassis Condition		الشاسي
09.A Chassis	OK, PORTION RUSTY	الشاسيه
10 Suspension System		ممتص الصدمات
10.A Suspension Subframe	BOTH SIDE SUBFRAME MOUNT RUBBER BEND	
10.B Arms	LOWER ARM BUSHES CRACKED	ازرع
10.C Ball Joint	BOOT CUT	مفصل كروي
11 Exhaust System		نظام العادم
11.A Other	PIPE CUT REWELDED	اخرى

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.