

Queue Number

2810719

Transaction Date

29 Sep 2026, 14:19:06

Site Name

840 - Emirates Auctions

Transaction Number

68625576 (CC10013) (CC10011)



Vehicle Details

Chassis Number	1J4BA2D18A*****
Specification	GCC Specification
Make	Jeep
Model	Wrangler
Model Year	2010
Color	Blue
Mileage	130287 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	6

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Fenders	FRONT BOTH SIDE REFITTED	مدكار
01.B Paint	BODY REPAINTED PORTION REPAIRED , MINOR DENT SCRATCHES PORTION RUSTY , PORTION FIBER	الصبغ
01.C Doors	RIGHT SIDE REFITTED	أبواب
01.D Rusty	UNDER FLOOR SUSPENSION PARTS RUSTY	صدأ
01.E Floor	UNDER FLOOR BODY MOUNT RUBBER DRY CRACK	الارضية
01.F Bumper	MISALIGN , MINOR SCRATCHES PORTION FADED	دعامية
01.G Roof	FRONT HARD TOP MISSING , REAR PORTION DAMAGE	السقف
01.H Bonnet	PORTION STICKER	غطاء المحرك
01.I Pillars	RIGHT SIDE ROCKER PANEL REPAIRED	القوائم
01.J Other	RIGHT SIDE FOOT STEP MISSING	اخرى
01.K Trunk	TAIL GATE UPPER BRACKET REFITTED	صندوق
01.L Fuel Tank	COVER RUSTY HOLE	خزان الوقود

02 Chassis Condition

الشاسي

02.A Chassis	CHASSIS FRAME GETTING RUSTY PORTION REPAINTED PORTION BULGED	الشاسيه
02.B Chassis Number	VIN AREA GETTING RUSTY / DOOR POST STICKER WORN OUT	رقم القاعدة

03 Engine Condition

المحرك

Condition	Remarks	الحالة
03.A Mount	MOUNT RUBBER DRY CRACK	كرسي
03.B Smoke	WHITE	دخان
03.C Engine Visual Condition	OIL LEAK , SHAKING , MISFIRING , OIL PAN DENT , COMPONENTS REFITTED , PARTS GETTING RUSTY	الحالة النظرية للمحرك
04 Seats Condition		المقاعد
04.A Seat Condition	PORTION CRACK	حالة المقاعد
05 Transmission Condition		الجير
05.A Gear Box Visual Condition	OIL LEAK ,COMPONENTS REFITTED , PARTS GETTING RUSTY	الحالة النظرية للجير
05.B Road Test	NOT CHECKED	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2018 CRACK EXPIRED	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2023	الاطار الخلفي
07 Lights		الاضاءة
07.A Indicator & Hazard light	FRONT LEFT SIDE INDICATOR DAMAGED	الاشارات
07.B Brake Light	LEFT SIDE NOT WORKING	نور الفرامل
08 Suspension System		ممتص الصدمات
08.A Arms	ARM BUSHES DRY CRACK	ازرع
09 Interior Condition		الحاله الداخليه
09.A Other	CENTER CONSOLE BOX PANEL PORTION WORN OUT, INTERIOR PARTS GETTING RUSTY	اخرى
09.B Mirror	CENTER VIEW MIRROR GETTING FADED	المرآيا
09.C AC Condition	NO COOLING , VENT GRILL LOOSE	المكيف
09.D Floor Matting	EXTRA COVER , LOOSE	فرش الأرضيه
09.E Dash Board	LOWER PANEL COVER MISSING ,PORTION WORN OUT , GLOVE BOX DAMAGE	لوحة القيادة
09.F Roof Ceiling	PORTION WORN OUT	بطانه السقف
09.G Sun Visor	BOTH SIDE LOOSE GLASS FADED AND COVER MISSING	حاجب الشمس
09.H Door Panel	PORTION WORN OUT	لوحة بطانة الباب
09.I Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
09.J Gear Shifting Lever	WORN OUT	ذراع نقل السرعات
10 Battery Condition		حالة البطارية
10.A Battery bracket	MISSING	حامل البطارية

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

للاشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae