

Queue Number

2747457

Transaction Date

14 Sep 2026, 15:27:42

Site Name

840 - Emirates Auctions

Transaction Number

76263137 (CC10009) (CC10012)



Vehicle Details

Chassis Number	WDDHF5EB8C*****
Specification	GCC Specification
Make	Mercedes
Model	C 300
Model Year	2012
Color	Beige
Mileage	260066 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	6

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Fenders	FRONT RIGHT SIDE , REAR LEFT SIDE REPAINTED	مدكار
01.B Paint	BODY PORTION REPAINTED PORTION REPAIRED MINOR DENT SCRATCHES	الصبغ
01.C Doors	RIGHT SIDE BOTH REPAINTED PORTION REPAIRED	أبواب
01.D Rusty	UNDER BODY PARTS GETTING RUSTY	صدأ
01.E Floor	FLOOR CHASSIS NOT VISIBLE, REMOVE ALL UNDER COVERS FOR RECHECK PROPERLY	الارضية
01.F Windshield	FRONT SPOT CRACK , REAR CURTAIN NOT WORKING	زجاج
01.G Roof	RIGHT SIDE SKIRT PORTION FADED	السقف
01.H Bonnet	LOGO DAMAGED	غطاء المحرك
01.I Sign of front accident	FRONT BUMPER BULK HEAD ASSEMBLY REFITTED	وجود مؤشر لحادث في المقدمة
01.J Vehicle Model	E300	طراز المركبة

02 Chassis Condition

الشاسي

02.A Chassis	CHASSIS COMPLETELY COVERED CHECKED VISIBLE AREA ONLY/OK	الشاسيه
--------------	---	---------

03 Engine Condition

المحرك

03.A Smoke	MINOR BLACK	دخان
03.B Engine Visual Condition	OIL LEAK PARTS REFITTED SHAKING GETTING RUSTY	الحالة النظرية للمحرك

04 Transmission Condition

الجير

Condition	Remarks	الحالة
04.A Gear Box Visual Condition	PARTS GETTING RUSTY DELAY SHIFTING	الحالة النظرية للجير
04.B Road Test	NOT CHECKED	فحص علي الطريق
05 Tires and Rims Condition		الاطارات
05.A Front Tyre	BOTH SIDE 2023 CRACK	الاطار الامامي
05.B Rear Tyre	BOTH SIDE 2023 CRACK	الاطار الخلفي
05.C Rims Condition	MINOR DENT SCRATCHES	حالة الجنوط
06 Lights		الاضاءة
06.A Tail Light	LEFT SIDE CRACK	الضوء الخلفي
07 Suspension System		ممتص الصدمات
07.A Arms	BUSHES CRACKED	ازرع
07.B Ball Joint	BOOT CUT	مفصل كروي
08 Interior Condition		الحاله الداخليه
08.A Other	CENTER CONSOLE BOX COVER PORTION MISSING	اخرى
08.B Mirror	BOTH SIDE LOOSE	المرايا
08.C AC Condition	OK , BUTTON PORTION FADED	المكيف
08.D Power Window Switch And Glass	BUTTON FADED	مفتاح النافذه و الزجاج
08.E Dash Board	LEATHER REPLACED , GRILL PORTION MISSING	لوحة القيادة
08.F Roof Ceiling	PORTION LOOSE	بطانه السقف

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

For complaints and inquiries reach out to us on wecare@carscheck.ae

لشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae