

Queue Number 2807933

Transaction Date 28 Sep 2026, 15:39:51

Site Name
840 - Emirates AuctionsTransaction Number
14123357 (CC10009) (CC10012)

Vehicle Details

Chassis Number	WBA11EH02R*****
Specification	GCC Specification
Make	BMW
Model	735 I
Model Year	2024
Color	Black
Mileage	34932 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	6

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Fenders	REPAINTED PORTION REPAIRED , FRONT RIGHT SIDE REFITTED	مدكار
01.B Paint	BODY PORTION REPAINTED PORTION REPAIRED MINOR DENT SCRATCHES	الصبغ
01.C Doors	REAR LEFT SIDE REPAINTED PORTION REPAIRED	أبواب
01.D Rusty	UNDER BODY PARTS GETTING RUSTY	صدأ
01.E Floor	FLOOR PORTION DENT, FRONT CHASSIS COVERED	الارضية
01.F Bumper	MISALIGN , MINOR CRACK , GRILL BRACKET CRACK MISALIGN	دعامية
01.G Windshield	REAR CURTAIN NOT WORKING	زجاج
01.H Bonnet	REPAINTED PORTION REPAIRED	غطاء المحرك
01.I Trunk	MISALIGN , LOGO WORN OUT	صندوق
01.J Sign of front accident	FRONT BUMPER FRAME BULK HEAD REPAIRED LEFT SIDE FRAME BNED	وجود مؤشر لحادث في المقدمة

02 Chassis Condition

الشاسي

02.A Chassis	CHASSIS COVERED CHECKED VISIBLE AREA ONLY/OK	الشاسيه
02.B Other	FOR RECHECK REMOVE ALL UNDER FENDER COVERS AND MAKE STEAM WASH	اخرى

03 Engine Condition

المحرك

03.A Engine Visual Condition	PARTS GETTING RUSTY MINOR SHAKING, TOP COVER MISSING	الحالة النظرية للمحرك
------------------------------	--	-----------------------

04 Transmission Condition

الجير

Condition	Remarks	الحالة
04.A Gear Box Visual Condition	PARTS GETTING RUSTY	الحالة النظرية للجير
04.B Road Test	NOT CHECKED	فحص علي الطريق
05 Tires and Rims Condition		الاطارات
05.A Front Tyre	BOTH SIDE 2023	الاطار الامامي
05.B Rear Tyre	BOTH SIDE 2023	الاطار الخلفي
05.C Rims Condition	MINOR DENT SCRATCHES	حالة الجنوط
06 Interior Condition		الحالة الداخلية
06.A Other	WATER FLOODED , (INTERIOR REFITTED, PANEL COVER PORTION MISSING , PORTION LOOSE) , CENTER CONSOLE BOX LEFT SIDE CUP HOLDER TOP COVER MISSING, ELECTRIC FUALT	اخرى
06.B AC Condition	NOT COOLING	المكيف
06.C Power Window Switch And Glass	CENTER LOCK NOT WORKING , REAR BOTH SIDE CURTAIN NOT WORKING	مفتاح النافذه و الزجاج
06.D Floor Matting	PORTION DAMAGED	فرش الأرضية
06.E Audio	LCD NOT WORKING	صوتيات
06.F Door Panel	MINOR WORN OUT	لوحة بطانة الباب
06.G Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
07 Battery Condition		حالة البطارية
07.A Battery bracket	MISSING	حامل البطارية

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

For complaints and inquiries reach out to us on wecare@carscheck.ae

للشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae