CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2905907
Transaction Date	26 Oct 2026, 11:16:39
Site Name	840 - Emirates Auctions
Transaction Number	12245379 (CC10010) (CC10010)



Vehicle Details

Chassis Number	MDHBN7ADXE*******
Specification	GCC Specification
Make	Nissan
Model	Sunny
Model Year	2014
Color	White
Mileage	769620 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Fenders	REPAINTED ,REFITTED.	مدكار
01.B Paint	BODY PORTION REPAINTED, PORTION REPAIRED DENTS, SCRATCHES , PORTION RUSTY, PORTION FADED	الصبغ
01.C Doors	PORTION REPAINTED	أبواب
01.D Rusty	UNDER BODY SUSPENSION PARTS GETTING RUSTY.	صدأ
01.E Floor	UNDER FLOOR PORTION DENT ,MUDDY.,	الارضية
01.F Bumper	MISALIGN,SCRATCHES , LOOSE ,PORTION DAMAGED.	دعامية
01.G Bonnet	REPAINTED REFITTED .	غطاء المحرك
01.H Sign of front accident	FRONT BUMPER FRAME , RADIATOR SUPPORT BULK HEAD,FENDER FRAME CROSS MEMBER REPAIRED.	وجود مؤشر لحادث في المقدمة
01.I Sign of back accident	BACK PANEL DENT.	وجود مؤشر لحادث في الخلف
02 Chassis Condition		الشاصي
02.A Chassis	FRONT CHASSIS END DENT GETING RUSTY , PORTION MUDDY ,OILY /.	الشاسيه
03 Engine Condition		المحرك
03.A Smoke	WHITE	دخان
03.B Engine Visual Condition	REFITTED OIL LEAK,SHAKING ,ABNORMAL NOISY. PARTS RUSTY	الحالة النظريه للمحرك
04 Seats Condition		المقاعد

Condition	Remarks	الحالة
04.A Seat Condition	DIRTY LOOSE PORTION CUT .	حالة المقاعد
05 Transmission Condition		الجير
05.A Gear Box Visual Condition	REFITTED OIL LEAK ,JERKING ,COMPONENT PARTS RUSTY.	الحالة النظريه للجير
05.B Road Test	NOT CHECKED .	فحص علي الطريق
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2024 CRACKED.	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2024 CRACKED.	الاطار الخلفي
06.C Rims Condition	DENTS SCRATCHES .	حالة الجنوط
07 Lights		الاضاءة
07.A Head Light	LENS FADED.	الاضاءة الرئيسية
07.B Tail Light	CRACKED	الضوء الخلفي
07.C Indicator & Hazard light	FENDER INDICATOR MISSING	الاشارات
07.D Warning Light	EXTRA WARNING LIGHT ON IN CLUSTER	ضوء تحذير
08 Brake Condition		الفرامل
08.A Brake Pedal	SPONGY	دواسة الفرامل
08.B Disc&Drum	RUSTY.	دسك وطنابير الفرامل
09 Suspension System		ممتص الصدمات
09.A Shock Absorber	LEAK.	ممتص الصدمات
09.B Arms	BUSHES CUT.	ازرع
10 Steering Condition		المقود
10.A Steering Boot	CUT .	ربلة المقود
10.B Steering Box	OIL LEAK .	جهاز المقود
11 Interior Condition		الحاله الداخليه
11.A Other	INTERIOR PARTS GETTING RUSTY ,SIGN OF FLOODED	اخري
11.B AC Condition	NOT COOLING.	المكيف
11.C Power Window Switch And Glass	RIGHT SIDE NOT WORKING	مفتاح النافذه و الزجاج
11.D Dash Board	PORTION LOOSE	لوحة القياده
11.E Door Panel	WORN OUT PORTION LOOSE	لوحة بطانة الباب
11.F Gear Shifting Lever	KNOB WORN OUT	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the

vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر **wecare@carscheck.ae**