



## TEST CERTIFICATE

Site Number	<b>840-Emirates Auctions</b>	Transaction Date	<b>04 Dec 2022, 17:15:30</b>
Transaction Number	<b>93432763 (CC10010)</b>	Queue Number	<b>635588</b>



Chassis Number	<b>JTGJX02P580012430</b>
Engine Number	
Vehicle Class	<b>Car</b>
Manufacturer	<b>Toyota</b>
Model	<b>Hiace</b>
Model Year	<b>2008</b>
Color	<b>White</b>
Mileage	<b>235346 Km</b>
Fuel Type	<b>Petrol</b>
No. Of Cylinders	<b>4</b>
Specification	<b>GCC Specification</b>

DEFECT	REMARKS	
<b>01 Interior Condition</b>		<b>الحاله الداخليه</b>
01.A Dash Board	MINOR HOLE	لوحة القيادة
01.B Other	GEAR LEVER DUST COVER PORTION DAMAGED	اخرى
01.C AC Condition	OK	المكيف
<b>02 Body</b>		<b>جسم المركبة</b>
02.A Paint	BODY PORTION REPAINTED,PORTION REPAIRED,MINOR DENT,SCRATCHES,PORTION STICKER	الصبغ
02.B Other	REAR CABIN HAVE EXTRA GRILL.	اخرى
02.C Bumper	MISALIGN ,REAR BRACKET LOOSE .	دعامية
02.D Roof	HAVE EXTRA HOLE ,PORTION GETTING RUSTY.	السقف
02.E Floor	PORTION DENT .	الارضية
02.F Rusty	UNDER BODY ,SUSPENSION PARTS GETTING RUSTY .	صدأ
<b>03 Seats Condition</b>		<b>المقاعد</b>
03.A Seat Condition	PORTION DAMAGED	حالة المقاعد
<b>04 Steering Condition</b>		<b>المقود</b>
04.A Steering Box	OIL LEAK.	جهاز المقود

DEFECT	REMARKS	
<b>05 Suspension System</b>		<b>ممتص الصدمات</b>
05.A Other	FRONT LEFT SIDE STUB/AXLE ONE MOUNT BOLT MISSING .	اخرى
<b>06 Engine Condition</b>		<b>المحرك</b>
06.A Visual Engine Condition	OIL LEAK.	حالة المحرك النظري
<b>07 Transmission Condition</b>		<b>الجير</b>
07.A Visual Gear Box Condition	MINOR OIL LEAK.	حالة الجير النظري
07.B Road Test	NOT CHECK	فحص علي الطريق
<b>08 Tires and Rims Condition</b>		<b>الاطارات</b>
08.A Rear Tyre	BOTH SIDE 2018 CRACKED,	الاطار الخلفي
08.B Front Tyre	BOTH SIDE 2018 CRACKED,	الاطار الامامي
<b>09 Lights</b>		<b>الاضاءة</b>
09.A Head Light	LENS FADED	الاضاءة الرئيسية
<b>10 Chassis Condition</b>		<b>الشاسي</b>
10.A Chassis	OK	الشاسيه

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.