CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2899747
Transaction Date	28 Oct 2026, 10:11:00
Site Name	840 - Emirates Auctions
Transaction Number	35495286 (CC10010) (CC10010)



Vehicle Details

Chassis Number	JTDKW92377*******
Specification	GCC Specification
Make	Toyota
Model	Yaris
Model Year	2007
Color	Silver
Mileage	389674 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Paint	BODY REPAINTED, PORTION REPAIRED DENTS, SCRATCHES , PORTION RUSTY, PORTION FADED	الصبغ
01.B Rusty	UNDER BODY SUSPENSION PARTS GETTING RUSTY.	صدأ
01.C Floor	UNDER FLOOR PORTION DENT ,MUDDY.,	الارضية
01.D Bumper	MISALIGN,SCRATCHES , LOOSE ,PORTION DAMAGED.	دعامية
01.E Sign of front accident	BULKHEAD ,RADIATOR SUPPORT REPAIRED.	وجود مؤشر لحادث في المقدمة
01.F Sign of side accident	LEFT SIDE FLOOR ING RUNNING BOARD, ROCKER PANEL,PILLAR OUTER PANEL REPAIRED ,	وجود مؤشر لحادث في الجانب
01.G Sign of back accident	BUMPER FRAME ,BACK PANEL REPAIRED CRACH BOX KINK .	وجود مؤشر لحادث في الخلف
02 Chassis Condition		الشاصي
02.A Chassis	REAR CHASSIS EXTENSION END DENT ,FRONT LEFT SIDE CHASSIS INNER SKIRT MINOR DENT .	الشاسيه
03 Engine Condition		المحرك
03.A Engine Visual Condition	ENGINE NOT START ,ALL SYSTEM NOT CHECKED ,REFITTED OIL LEAK,PARTS RUSTY	الحالة النظريه للمحرك
04 Transmission Condition		الجير
04.A Gear Box Visual Condition	NOT CHECKED ,REFITTED,OIL LEAK ,COMPONENT PARTS RUSTY .	الحالة النظريه للجير
04.B Road Test	NOT CHECKED.	فحص علي الطريق

Condition	Remarks	الحالة
05 Tires and Rims Condition		الاطارات
05.A Front Tyre	BOTH SIDE 2024 DRY CRACKED.	الاطار الامامي
05.B Rear Tyre	BOTH SIDE 2024 DRY CRACKED.	الاطار الخلفي
06 Lights		الاضاءة
06.A Head Light	LENS FADED, ALL LIGHTS NOT CHECK	الاضاءة الرئيسية
07 Brake Condition		الفرامل
07.A Disc&Drum	PARTS RUSTY.	دسك وطنابير الفرامل
08 Suspension System		ممتص الصدمات
08.A Shock Absorber	LEAK .	ممتص الصدمات
08.B Arms	BUSHES CUT .	ازرع
09 Steering Condition		المقود
09.A Steering Boot	CRACKED .	ربلة المقود
09.B Steering Box	OIL LEAK .	جهاز المقود
10 Interior Condition		الحاله الداخليه
10.A Other	INTERIOR PARTS GETTING RUSTY ,SIGN OF FLOODED	اخري
10.B AC Condition	NOT CHECKED .	المكيف
10.C Dash Board	GLOVE BOX LOOSE.	لوحة القياده
10.D Sun Visor	LOOSE.	حاجب الشمس
10.E Door Panel	WORN OUT PORTION LOOSE.	لوحة بطانة الباب
10.F Steering Wheel and control buttons	WORN OUT .	عجلة القيادة وازرار التحكم
10.G Gear Shifting Lever	KNOB WORN OUT .	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae