



TEST CERTIFICATE

Site Number **840-Emirates Auctions** Transaction Date **05 Sep 2022, 18:02:37**
 Transaction Number **79169277 (CC10008)** Queue Number **312309**



Chassis Number **WBAFR1101DC861323**
 Engine Number
 Vehicle Class **Car**
 Manufacturer **BMW**
 Model **530I**
 Model Year **2013**
 Color **White**
 Mileage **302818 Km**
 Fuel Type **Petrol**
 No. Of Cylinders **6**
 Specification **GCC Specification**

DEFECT	REMARKS	
01 Interior Condition		الحاله الداخليه
01.A Roof Ceiling	LOOSE	بطانه السقف
01.B Dash Board	DASHBOARD DAMAGED PORTION MODIFIED SIDE COVER LOOSE	لوحة القيادة
01.C AC Condition	LOW COOLING	المكيف
01.D Audio	SCREEN MISSING	صوتيات
02 Body		جسم المركبة
02.A Fenders	FRONT RIGHT SIDE & REAR BOTH SIDE PORTION REPAIRED,REPAINTED	مدكار
02.B Doors	PORTION REPAIRED,REPAINTED	أبواب
02.C Bonnet	PORTION REPAIRED,REPAINTED,REFITTED,SHOCK WEAK	غطاء المحرك
02.D Trunk	REPAIRED,REPAINTED	صندوق
02.E Roof	DEEP DENT,PORTION HAVE HOLE	السقف
02.F Floor	UNDER FLOOR CHASSIS FENDER FULLY COVERED CHECKED VISIBLE AREA	الارضية
02.G Paint	BODY PORTION REPAIRED, REPAINTED,MINOR DENT,SCRATCHES	الصبغ
02.H Pillars	PILLAR OUTER PANEL PORTION REPAIRED,REPAINTED	القوائم

DEFECT	REMARKS	
03 Transmission Condition		الجير
03.A Visual Gear Box Condition	MINOR OIL LEAK	حالة الجير النظرى
03.B Road Test	NOT CHECK	فحص علي الطريق
04 Steering Condition		المقود
04.A Tie Rod End	BOOT CUT	مؤخرة الرودادت
05 Suspension System		ممتص الصدمات
05.A Ball Joint	BOOT CUT	مفصل كروي
05.B Arms	LOWER ARM BUSHES CUT	ازرع
06 Engine Condition		المحرك
06.A Visual Engine Condition	MINOR OIL LEAK, ABNORMAL NOISY SHAKING	حالة المحرك النظرى
07 Chassis Condition		الشاصي
07.A Chassis	CHECKED VISIBLE AREA OK	الشاسيه
08 Tires and Rims Condition		الاطارات
08.A Front Tyre	BOTH SIDE 2019	الاطار الامامي
08.B Rear Tyre	BOTH SIDE 2019 MINOR CRACKED	الاطار الخلفي
09 Lights		الاضاءة
09.A Warning Light	WARNING LIGHT ON DISPLAY	ضوء تحذير

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.