

Queue Number 2855832

Transaction Date 10 Oct 2026, 12:45:46

Site Name
840 - Emirates AuctionsTransaction Number
86922892 (CC10009) (CC10019)

Vehicle Details

Chassis Number	WBS2U7A01K*****
Specification	GCC Specification
Make	BMW
Model	M2
Model Year	2019
Color	White
Mileage	49384 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	6

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Fenders	FRONT REFITTED	مدكار
01.B Paint	BODY TOTALY STICKER , BODY PORTION REPAINTED PORTION REPAIRED PAINT NOT CHECK PROPERLY	الصبغ
01.C Rusty	UNDER BODY PARTS ,POWER TRAIN GETTING RUSTY	صدأ
01.D Floor	UNDER FLOOR CHASSIS COVERED CHECKED VISIBLE AREA ONLY ,FLOOR COVERED MUDDY	الارضية
01.E Bumper	MISALIGN	دعامية
01.F Trunk	REFITTED,SWITCH NOT WORKING	صندوق
01.G Sign of front accident	FRONT BUMPER FRAME BUL HEAD LEFT SIDE FENDER FRAME REPAIRED	وجود مؤشر لحادث في المقدمة
01.H Sign of side accident	REAR LEFT SIDE WHEEL ARCH QUARTER PANEL REPAIRED	وجود مؤشر لحادث في الجانب

02 Chassis Condition

الشاسي

02.A Chassis	CHASSIS COMPLETELY COVERED CHECKED VISIBLE AREA ONLY/OK	الشاسيه
--------------	---	---------

03 Engine Condition

المحرك

03.A Engine Visual Condition	SIGN OF OIL WET, PARTS REFITTED	الحالة النظرية للمحرك
------------------------------	---------------------------------	-----------------------

04 Transmission Condition

الجير

04.A Gear Box Visual Condition	PARTS GETTING RUSTY	الحالة النظرية للجير
04.B Road Test	NOT CHECKED	فحص علي الطريق

Condition	Remarks	الحالة
05 Tires and Rims Condition		الاطارات
05.A Front Tyre	BOTH SIDE 2024	الاطار الامامي
05.B Rear Tyre	BOTH SIDE 2024	الاطار الخلفي
05.C Rims Condition	MINOR DENT SCRATCHES	حالة الجنوط
06 Interior Condition		الحالة الداخليه
06.A Other	INTERIOR PARTS GETTING MINOR RUSTY ,SIGN OF FLOODED	اخرى
06.B AC Condition	OK	المكيف

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

For complaints and inquiries reach out to us on wecare@carscheck.ae

للتشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae