



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	28 Jun 2022, 16:00:29
Transaction Number	30408007 (CC10006)	Queue Number	312309



Chassis Number	JMYSRCY1AFU724785
Engine Number	
Vehicle Class	Car
Manufacturer	Mitsubishi
Model	Lancer
Model Year	2015
Color	White
Mileage	206291 Km
Fuel Type	Petrol
No. Of Cylinders	4
Specification	GCC Specification

DEFECT	REMARKS	
01 Transmission Condition		الجير
01.A Visual Gear Box Condition	SIGN OF MINOR OIL LEAK	حالة الجير النظرى
01.B Gear Box Mount	MOUNT BUSH CUT	كرسي الجير
01.C Road Test	NOT CHECK	فحص علي الطريق
02 Suspension System		ممتص الصدمات
02.A Arms	FRONT LOWER ARM BUSH CRACKED	ازرع
03 Body		جسم المركبة
03.A Paint	BODY PORTION REPAIRED , REPAINTED & MINOR DENT ,SCRATCHES	الصبغ
03.B Trunk	PORTION REPAIRED,REPAINTED	صندوق
03.C Bumper	MISALIGN,REPAINTED	دعامية
03.D Pillars	LEFT SIDE A/PILLAR, ROCKER PANEL, WHEEL HOUSING & RUNNING BOARD REPAIRED REPAIRED	القوائم
03.E Rusty	UNDER BODY PARTS GETTING RUSTY	صدأ
03.F Fenders	FRONT SIDE BOTH & REAR LEFT SIDE PORTION REPAIRED, REPAINTED	مدكار
03.G Doors	LEFT SIDE BOTH PORTION REPAIRED,REPAINTED	أبواب

DEFECT	REMARKS	
03.H Bonnet	PORTION REPAIRED , REPAINTED & REFITTED	غطاء المحرك
03.I Other	FRONT FENDER FRAME, RADITOR SUPPORT, BUMPER FRAME , BULKHEAD REPAIRED	اخرى
03.J Sign of front accident		وجود مؤشر لحادث في المقدمة
04 Chassis Condition		الشاسيه
04.A Chassis	FRONT BOTH SIDE END REPAIRED & LEFT SIDE INNER KINK & BEND	الشاسيه
05 Tires and Rims Condition		الاطارات
05.A Front Tyre	BOTH SIDE 2020	الاطار الامامي
05.B Rear Tyre	BOTH SIDE 2018	الاطار الخلفي
06 Interior Condition		الحاله الداخليه
06.A AC Condition	OK	المكيف
07 Engine Condition		المحرك
07.A Visual Engine Condition	SIGN OF MINOR OIL LEAK	حالة المحرك النظري
07.B Mount	MOUNT BUSH CUT	كرسي

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

Test Certificate



Vehicle
Registration



✓ PASS

Possession Certificate :	65830870
Chassis No :	JMYSRCY1AFU724785
Vehicle Make :	MITSUBISHI
Vehicle Model :	LANCER
Vehicle Class :	Light Vehicle
Body Type :	SALOON
Fuel :	Benzene
Color :	White
Drive Direction :	--
Dimensions : (H x W x L)	-- x -- x --
Current Odometer :	206292 Kms.
Origin :	Japan
Model Year :	2015
Gear Type :	Automatic
Engine No :	4A92BT4010
Axles No :	2
No Of	4
Doors :	
G. V. W. :	1650 Kgs.
Model Year :	2015
Engine Size :	1600 CC
Horse	--
Power :	
Cylinders :	4
No Of Seats :	5
Empty	1110 Kgs.
Weight :	

Certificate Number :	5-TAS-2022-17140562
Inspection Date :	04-07-2022
Certificate Print Date :	04-07-2022
Services :	Registration Test
Vehicle Testing Partner :	Tasjeel
Vehicle Testing Center :	Tasjeel Al Aweer
Total Time Taken :	12 min 41 sec
Appointment Ref Number :	--
Start Time :	13:11
End Time :	13:24
Lane :	01
Attempt :	1
Token No. :	162
Prints No. :	1

Carbon footprint



Thank you! You are environment protector

Estimated Vehicle Consumption (Rate last 12 Months)

22070 KM	1569 L	2542 AED	3.8 ton
Distance per year	Fuel consumed per year	Fuel cost per year	Carbon footprint per year

Parameter Readings

Service brake imbalance on front axle	Service brake imbalance on rear axle	Parking brake imbalance between LHS and RHS	Vehicle on Petrol CO Reading
3 %	20 %	13 %	0.45 %
Vehicle on Petrol HC Reading			
128 PPM VOL			

Inspection Remarks:

FRONT LEFT SIDE ENDFRONT RIGHT INNER CHASSIS DENT MINOR DENT,BULK HEAD,RADIATOR SUPPORT & REAR BUMPER FRAME,VALANCE PANEL,SPARE WHEEL HOUSE REPAIRED

Payment Details

Inspection Performed by	Payment Method	Transaction Number	Service Fees
62439	Cash	17140562	AED 170 Collected on 04/07/2022
Parking Slot No	Service Name	Attempt	Received by
--	Registration Test	1	Sittu Paloth Sreesan Paloth

1 This is to acknowledge the receipt of AED 170 (in words: One Hundred and Seventy Dirhams Only.), towards the above service.

2 Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations.

تستخدم هذه الشهادة حصرا في العمليات الخاصة بالترخيص الفني للمركبة. لا يعتد بهذه الشهادة لأي عمليات أخرى بما في ذلك أغراض البيع أو الشراء خلف عملية ترخيص المركبة. لا تتحمل الجهة المصدرة أية مسؤولية جراء استعمال هذه الشهادة لغير ما أصدرت من أجله. هذه الشهادة صالحة لإجراء معاملة واحدة فقط خلال 30 يوم من تاريخ الفحص.



This certificate is used exclusively in the technical licensing process for vehicle. This certificate should not be valid for any process including selling or buying purposes other than vehicle licensing process. The issuing entity shall not bear any liability for using this certificate for any purposes other than those it was issued for. This certificate is valid for one transaction only for 30 days from the date of inspection.