

Queue Number 2393245

Transaction Date 16 May 2026, 12:13:23

Site Name
840 - Emirates AuctionsTransaction Number
16298314 (CC10009) (CC10019)

Vehicle Details

Chassis Number	LMWHA1G84N*****
Specification	GCC Specification
Make	GAC
Model	GS3
Model Year	2022
Color	Black
Mileage	327697 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Fenders	REAR RIGHT SIDE REPAINTED PORTION REPAIRED,	مدكار
01.B Paint	BODY PORTION REPAINTED PORTION REPAIRED,MINOR DENT SCRATCHES,PORTION RUSTY	الصبغ
01.C Rusty	UNDER BODY PARTS GETTING RUSTY	صدأ
01.D Bumper	MISALIGN	دعامية
01.E Windshield	FRONT SPOT CRACKED	زجاج
01.F Roof	STICKER PAINT NOT CHECKED	السقف
01.G Pillars	RIGHT SIDE A/ PILLAR ROCKER PANEL,MINOR RUSTY	القوائم

02 Chassis Condition

الشاسي

02.A Chassis	CHASSIS PORTION RUSTY/OK	الشاسيه
--------------	--------------------------	---------

03 Engine Condition

المحرك

03.A Engine Visual Condition	OIL WET REFITTED GETTING RUSTY MINOR SHAKING	الحالة النظرية للمحرك
------------------------------	--	-----------------------

04 Seats Condition

المقاعد

04.A Seat Condition	DRIVER SEAT COVER PORTION WORN OUT	حالة المقاعد
---------------------	------------------------------------	--------------

05 Transmission Condition

الجير

05.A Gear Box Visual Condition	OIL WET REFITTED GETTING RUSTY	الحالة النظرية للجير
05.B Road Test	NOT CHECKED	فحص علي الطريق

Condition	Remarks	الحالة
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2023 CRACKED	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2023 CRACKED	الاطار الخلفي
06.C Rims Condition	MINOR DENT SCRATCHES	حالة الجنوط
07 Suspension System		ممتص الصدمات
07.A Arms	BUSHES CRACKED	ازرع
07.B Ball Joint	BOOT CUT	مفصل كروي
08 Interior Condition		الحالة الداخلية
08.A Other	INTERIOR PARTS GETTING RUSTY, SIGN OF FLOODED	اخرى
08.B Mirror	CENTER MIRROR PORTION LOOSE	المرآيا
08.C AC Condition	OK	المكيف
08.D Door Panel	PORTION CRACKED	لوحة بطانة الباب
08.E Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
08.F Sunroof	NOT WORKING PROPERLY	فتحت سقف
08.G Gear Shifting Lever	KNOB WORN OUT	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

For complaints and inquiries reach out to us on wecare@carscheck.ae

للشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae