



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	18 May 2023, 13:44:25
Transaction Number	93869020 (CC10013)	Queue Number	720978



Chassis Number	1N4AL3AP3DN450460
Engine Number	
Vehicle Class	Car
Manufacturer	Nissan
Model	Altima
Model Year	2013
Color	Black
Mileage	001 Km
Fuel Type	Petrol
No. Of Cylinders	4
Specification	GCC Specification

DEFECT	REMARKS	
01 Body		جسم المركبة
01.A Trunk	NOT OPEN FOR RECHECK	صندوق
01.B Floor	UNDER FLOOR PORTION DENT,S & PORTION GETTING RUSTY	الارضية
01.C Bumper	MISALIGN PORTION CRACK	دعامية
01.D Windshield	FRONT SPOT CRACK	زجاج
01.E Paint	BODY REPAINTED PORTION REPAIRED PORTION RUSTY MINOR DENT SCRATCHES	الصبغ
01.F Rusty	UNDER FLOOR SUSPENSION PARTS GETTING RUSTY	صدأ
01.G Pillars	LEFT SIDE A PILLAR DOOR POST RIGHT SIDE B,C PILLAR & ROCKER PANEL REPAIRED	القوائم
02 Engine Condition		المحرك
02.A Visual Engine Condition	ENGINE NOT START ALL SYSTEM NOT CHECK KEY MISSING OIL WET	حالة المحرك النظري
02.B Other	ENGINE COMPARTMENT FULLY MUDDY & INNER SHOCK SUPPORT ROD BEND	اخرى
03 Interior Condition		الحالة الداخليه
03.A Other	INTERIOR CONDITION FULLY MUDDY	اخرى

DEFECT	REMARKS	
03.B AC Condition	NOT CHECK	المكيف
03.C Door Panel	PORTION WORN OUT	لوحة بطانة الباب
03.D Dash Board	PORTION PARTS WORN OUT LOOSE	لوحة القيادة
03.E Odometer reading	NOT CHECK	قراءة عداد المسافات
03.F Mirror	CENTER VIEW MIRROR GETTING FADED	المرايا
04 Transmission Condition		الجير
04.A Road Test	NOT CHECK	فحص علي الطريق
04.B Visual Gear Box Condition	NOT CHECK OIL WET	حالة الجير النظري
05 Steering Condition		المقود
05.A Steering Box	OIL WET	جهاز المقود
06 Battery Condition		حالة البطارية
06.A Battery bracket	MISSING	حامل البطارية
07 Lights		الاضاءة
07.A Head Light	LENS FADED ALL LIGHT NOT CHECK	الاضاءة الرئيسية
07.B Fog light	RIGHT SIDE PORTION CRACK	كشاف الضباب
08 Suspension System		ممتص الصدمات
08.A Arms	LOWER ARM BUSH CRACK	ازرع
08.B Suspension Subframe	MINOR DENT	
09 Chassis Condition		الشاصي
09.A Chassis	CHASSIS COVERED CHECKED VISIBLE AREA ONLY/OK	الشاسيه
09.B Chassis Number	DOOR POST STICKER GETTING FADED	رقم القاعدة
10 Brake Condition		الفرامل
10.A Disc&Drum	RUSTY	دسك ووطنابير الفرامل
11 Tires and Rims Condition		الاطارات
11.A Front Tyre	BOTH SIDE 2020 WORN OUT	الاطار الامامي
11.B Rims Condition	MINOR SCRATCHES	حالة الجنوط
11.C Rear Tyre	BOTH SIDE 2020 WORN OUT	الاطار الخلفي

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

