CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2968191
Transaction Date	10 Nov 2026, 16:08:41
Site Name	840 - Emirates Auctions
Transaction Number	15914988 (CC10009) (CC10019)



Vehicle Details

Chassis Number	WDCDF7DE3E*******
Specification	GCC Specification
Make	Mercedes
Model	GL 500
Model Year	2014
Color	Unknown
Mileage	229673 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	8

Condition	Remarks	الحالة
01 Body		**جسم المركبة**
01.A Paint	BODY MINOR DENT SCRATCHES,	الصبغ
01.B Rusty	UNDER BODY PARTS GETTING RUSTY	صدأ
01.C Floor	FLOOR CHASSIS COMPLETELY COVERED MUDDY	الارضية
01.D Bumper	MISALIGN,PORTION DAMAGED	دعامية
01.E Bonnet	RIGHT SIDE GRILL PORTION DAMAGED	غطاء المحرك
01.F Sign of front accident	FRONT BUMPER FRAME BULK HEAD REPAIRED,	وجود مؤشر لحادث في المقدمة
01.G Vehicle Color	WHITE	لون المركبة
02 Chassis Condition		**الشاصي**
02.A Chassis	CHASSIS COMPLETELY COVERED CHECKED VISIBLE AREA ONLY/OK	الشاسيه
02.B Other	REMOVE ALL UNDER FLOOR CHASSIS COVERS FOR RECHECK PROPERLY	اخري
03 Engine Condition		**المحرك**
03.A Other	LEFT SIDE AIR INTAKE PIPE DAMAGED	اخري
03.B Engine Visual Condition	MINOR OILLEAK PARTS REFITTED ABNORMAL NOISY GETTING RUSTY, HOLE COVER MISSING	الحالة النظريه للمحرك
04 Transmission Condition		**الجير**
04.A Gear Box Visual Condition	PARTS REFITTED GETTING RUSTY MINOR JERKING	الحالة النظريه للجير

Condition	Remarks	الحالة
04.B Gear Box Mount	MOUNT RUBBER CUT	كرسي الجير
04.C Road Test	NOT CHECKED	فحص علي الطريق
05 Tires and Rims Condition		**الاطارات**
05.A Front Tyre	BOTH SIDE 2024	الاطار الامامي
05.B Rear Tyre	BOTH SIDE 2024	الاطار الخلفي
05.C Rims Condition	MINOR DENT SCRATCHES	حالة الجنوط
06 Suspension System		**ممتص الصدمات**
06.A Arms	BUSHES CRACKED	ازرع
06.B Ball Joint	BOOT CUT	مفصل كروي
06.C Stabilizer Bar And Link Rod	BAR MOUNT RUBBER CUT	عمود التوازن و مثبت عمود التوازن
07 Interior Condition		**الحاله الداخليه**
07.A AC Condition	NOT COOLING	المكيف
07.B Power Window Switch And Glass	SWITCH PORTION FADED	مفتاح النافذه و الزجاج
07.C Dash Board	LEATHER MINOR LOOSE	لوحة القياده
07.D Sun Visor	LEFT SIDE COVER MIRROR PORTION DAMAGED	حاجب الشمس
07.E Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae