

Queue Number 2841420

Transaction Date 07 Oct 2026, 13:18:41

Site Name
840 - Emirates AuctionsTransaction Number
68173169 (CC10010) (CC10010)

Vehicle Details

Chassis Number	JN8BY2NY8M*****
Specification	GCC Specification
Make	Nissan
Model	Patrol
Model Year	2021
Color	Grey
Mileage	145284 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	6

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Fenders	FRONT FENDER ,REFITTED,REPAINTED .REAR BOTH QUARTER PANEL ,REPAINTED PORTION REPAIRED.	مدكار
01.B Paint	BODY PORTION REPAINTED PORTION REPAIRED,MINOR DENT SCRATCHES .	الصبغ
01.C Doors	LEFT SIDE BOTH DOORS REPAINTED PORTION REPAIRED.	أبواب
01.D Rusty	UNDER BODY PARTS, SUSPENTION GETTING RUSTY	صدأ
01.E Floor	UNDER FLOOR MUDDY, PORTION DENTS	الارضية
01.F Bumper	MODIFIED LOOSE. MISALIGN. PARKING SENSORS MISSING.	دعامية
01.G Bonnet	REFITTED .	غطاء المحرك
01.H Sign of front accident	FRONT BUMPER FRAME , FENDER FRAME ,BULKHEAD ,RADIATOR SUPPORT REPAIRED,CROSS MEMBER BODY MOUNT BRACKET BEND .	وجود مؤشر لحادث في المقدمة

02 Chassis Condition

الشاسي

02.A Chassis	FRONT RIGTH SIDECHASSIS @ LOADING POINT AREA OUTER SKIRT BEND KINK , CHASSIS GETING RUSTY .	الشاسيه
--------------	---	---------

03 Engine Condition

المحرك

03.A Other	AIR FILTER ASSEMBLY FIXED BY GLUE.	اخرى
03.B Engine Visual Condition	PARTS REFITTED ,OIL WET SHAKING ,ABNORMAL NOISY ,COMPONENT PARTS RUSTY.	الحالة النظرية للمحرك

04 Transmission Condition

الجير

Condition	Remarks	الحالة
04.A Gear Box Visual Condition	COMPONENT PARTS RUSTY GET JERKING.	الحالة النظرية للجير
04.B Road Test	NOT CHECKED .	فحص علي الطريق
05 Tires and Rims Condition		الاطارات
05.A Front Tyre	BOTH SIDE 2023 DRY CRACKED ,GETTING WORN OUT .	الاطار الامامي
05.B Rear Tyre	BOTH SIDE 2023 DRY CRACKED ,GETTING WORN OUT .	الاطار الخلفي
05.C Rims Condition	DENTS SCRATCHES .	حالة الجنوط
06 Lights		الاضاءة
06.A Head Light	LEND GETTING FADED ,RIGHT SIDE COVER MISSING.	الاضاءة الرئيسية
06.B Warning Light	EXTRA WARNING LIGHT ON IN CLUSTER.	ضوء تحذير
07 Brake Condition		الفرامل
07.A Brake Pedal	GETTING SPONGY.	دواسة الفرامل
07.B Disc&Drum	PARTS RUSTY.	دسك وطنابير الفرامل
08 Suspension System		ممتص الصدمات
08.A Shock Absorber	LEAK WEAK .	ممتص الصدمات
08.B Arms	BUSHES CRACKED.	ازرع
09 Interior Condition		الحالة الداخليه
09.A Other	INTERIOR MODIFIED ,COLOR CHANGED .	اخرى
09.B Dash Board	LEATHER REPLACED.	لوحة القيادة
09.C Roof Ceiling	INTERIOR MODIFIED.	بطانه السقف
09.D Air Bag	OPEN REFITTED .	وسائد هوائية
09.E Steering Wheel and control buttons	PORTION WORN OUT	عجلة القيادة وازرار التحكم
09.F Gear Shifting Lever	KNOB WORN OUT	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه

For complaints and inquiries reach out to us on wecare@carscheck.ae

لشكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae

