

TEST CERTIFICATE

الارضية

الصبغ

Site Number Transaction Number **840-Emirates Auctions** 56697141 (CC10009)

Transaction Date

08 Mar 2023, 14:01:02

Oueue Number 685027

Chassis Number

KMHWG81RXCU402375

Engine Number

Vehicle Class Car

Manufacturer Hyundai

Model H1

Model Year 2012

Color

Mileage 001 Km

Fuel Type Petrol

No. Of Cylinders

Specification **GCC Specification**



DEFECT REMARKS

Of Body	جسم المركبة
OT Body	جسم المركبة

01.A Other **VISUAL TEST ONLY** اخري 01.B Floor UNDER FLOOR PARTS CHASSIS SUSPENSION NOT

CHECKED

BODY PAINT NOT CHECKED PORTION RUSTY FADED 01.C Paint

01.D Vehicle Color WHITE لون المركبة

02 Chassis Condition الشاصي

02.A Chassis CHASSIS NOT CHECK الشاسيه

02.B Chassis Number VIN NUMBER CHECKED ONLY STICKER رقم القاعدة

03 Wipers and Arms المساحات

03.A Wiper Arm &Blade **REAR MISSING** ازرع المساحات والشفرات

04 Transmission Condition الجير

04.A Road Test NOT CHECK فحص علي الطريق

04.B Visual Gear Box **NOT CHECK** حالة الجير النظرى Condition

05 Tires and Rims Condition الاطارات

DEFECT	REMARKS	
05.A Front Tyre	CRACKED DATE NOT CHECK	الاطار الامامي
05.B Rear Tyre	CRACKED DATE NOT CHECKED	الاطار الخلفي
06 Engine Condition		المحرك
06.A Visual Engine Condition	ENGINE NOT START ALL SYSTEM NOT CHECKED	حالة المحرك النظرى
07 Lights		الاضاءة
07 Lights 07.A Head Light	LENS FADED & ALL LIGHT NOT CHECK	الاضاءة الاضاءة الرئيسية
	LENS FADED & ALL LIGHT NOT CHECK	
07.A Head Light	LENS FADED & ALL LIGHT NOT CHECK NOT CHECK	الاضاءة الرئيسية

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate,
 Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.