CAR CHECK

شهادة فحص مركبة
Vehicle Test Certificate

Queue Number	2971084
Transaction Date	12 Nov 2026, 08:40:54
Site Name	840 - Emirates Auctions
Transaction Number	45266164 (CC10009) (CC10011)



Vehicle Details

Chassis Number	WAUCFC8R2C*******
Specification	GCC Specification
Make	Audi
Model	Q5
Model Year	2012
Color	Brown
Mileage	236431 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition	Remarks	الحالة
01 Body		جسم المركبة
01.A Fenders	REPAINTED PORTION REPAIRED,FRONT REFITTED	مدكار
01.B Paint	BODY PORTION REPAINTED,PORTION REPAIRED,MINOR DENTS SCRATCHES,PORTION FADED	الصبغ
01.C Doors	FRONT BOTH SIDE,REAR LEFT REPAINTED PORTION REPAIRED	أبواب
01.D Rusty	UNDER BODY PARTS GETTING RUSTY	صدأ
01.E Floor	FLOOR COMPLETELY COVERED MUDDY OILY	الارضية
01.F Bumper	MISALIGN PORTION DAMAGED,LEFT SIDE REFLECTOR HAVE STICKER	دعامية
01.G Bonnet	REPAINTED PORTION REPAIRED	غطاء المحرك
01.H Trunk	PORTION REPAIRED REPAINTED	صندوق
02 Chassis Condition		الشاصي
02.A Chassis	CHASSIS COMP0LETELY MUDDY OILY CHECKED VISIBLE AREA OK	الشاسيه
03 Engine Condition		المحرك
03.A Smoke	WHITE	دخان
03.B Other	ENGINE PULLEY NOISY	اخري
03.C Engine Visual Condition	MINOR OIL LEAK, OPEN REFITTED ,PARTS GETTING RUSTY	الحالة النظريه للمحرك
04 Seats Condition		المقاعد
04.A Seat Condition	COVER PORTION WORN OUT,FRONT LEFT SEAT SIDE COVER PORTION DAMAGED,RIGHT SIDE WHILE ADJUSTMENT NOISY	حالة المقاعد

Condition	Remarks	الحالة
05 Transmission Condition		**الجير**
05.A Gear Box Visual Condition	REFITTED ,PARTS GETTING RUSTY	الحالة النظريه للجير
05.B Road Test	NOT CHECKED	فحص علي الطريق
06 Tires and Rims Condition		**الاطارات**
06.A Front Tyre	BOTH SIDE 2024 CRACKED	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2024 CRACKED	الاطار الخلفي
06.C Rims Condition	MINOR DENTS SCRATCHES	حالة الجنوط
07 Lights		**الاضاءة**
07.A Head Light	SWITCH DAMAGED,LENS FADED,RIGHT SIDE NOT WORKING CRACKED	الاضاءة الرئيسية
07.B Tail Light	NOT WORKING PORTION CRACKED	الضوء الخلفي
07.C Warning Light	WARNING LIGHTS ON DISPLAY	ضوء تحذير
08 Brake Condition		**الفرامل**
08.A Hand Brake	SWITCH WORN OUT	فرامل اليد
09 Interior Condition		**الحاله الداخليه**
09.A Other	INTERIOR PARTS GETTING MINOR RUSTY ,CENTER CONSOLE BOX COVER,PANEL PORTION WORN OUT	اخري
09.B Mirror	ADJUSTMENT NOT WORKING PROPERLY,CENTER VIEW MIRROR LOOSE BACK COVER PART MISSING	المرايا
09.C AC Condition	OK	المكيف
09.D Audio	SCREEN PORTION FADED	صوتيات
09.E Dash Board	GLOVE BOX COVER LOOSE LOCK BRACKET DAMAGED	لوحة القياده
09.F Door Panel	PORTION WORN OUT	لوحة بطانة الباب
09.G Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
09.H Sunroof	CURTAIN DAMAGED	فتحت سقف
09.I Gear Shifting Lever	KNOB WORN OUT,DUST COVER PORTION CRACK	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate

يمكنك التحقق من صحة الشهادة عبر الرابط
carcheck.ae/certificate

Terms & Conditions

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

الشروط والأحكام

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

For complaints and inquiries reach out to us on wecare@carscheck.ae

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة،
كما لا تضمن بموجب هذه الشهادة صلاحية المركبة
.للتسجيل من عدمه

للشكاوي والمقترحات يمكنك التواصل معانا عبر
wecare@carscheck.ae