

Queue Number 2827638

Transaction Date 10 Oct 2026, 12:45:34

Site Name
840 - Emirates AuctionsTransaction Number
73998100 (CC10021) (CC10021)

Vehicle Details

Chassis Number	LZWADAGA2P*****
Specification	GCC Specification
Make	Chevrolet
Model	Captiva
Model Year	2023
Color	White
Mileage	147446 Km
Fuel Type	Petrol
Transmission Type	
No. Of Cylinders	4

Condition

Remarks

الحالة

01 Body

جسم المركبة

01.A Fenders	FRONT RIGHT SIDE CHROME STRIP LOOSE,DAMAGED	مدكار
01.B Paint	BODY PORTION REPAINTED, PORTION REPAIRED, MINOR DENTS & SCRATCHES	الصبغ
01.C Rusty	UNDER BODY PARTS ,SUSPENSION GETTING RUSTY	صدأ
01.D Floor	NEED TO REMOVE FRONT BOTH SIDE FENDER INNER COVER FOR PROPER INSPECTION	الارضية
01.E Bumper	MISALIGN,LOOSE,PORTION DAMAGED	دعامية
01.F Bonnet	PORTION REPAINTED,PORTION REPAIRED	غطاء المحرك

02 Chassis Condition

الشاسي

02.A Chassis	CHASSIS COVERED,GETTING RUSTY CHECKED VISIBLE AREA ONLY / OK	الشاسيه
--------------	--	---------

03 Engine Condition

المحرك

03.A Engine Visual Condition	ENGINE NOT START ,ALL SYSTEM NOT CHECKED OPEN REFITTED PARTS RUSTY	الحالة النظرية للمحرك
------------------------------	--	-----------------------

04 Seats Condition

المقاعد

04.A Seat Condition	WORN OUT	حالة المقاعد
---------------------	----------	--------------

05 Transmission Condition

الجير

05.A Gear Box Visual Condition	NOT CHECKED REFITTED PARTS RUSTY	الحالة النظرية للجير
05.B Road Test	NOT CHECKED	فحص علي الطريق

Condition	Remarks	الحالة
06 Tires and Rims Condition		الاطارات
06.A Front Tyre	BOTH SIDE 2025	الاطار الامامي
06.B Rear Tyre	BOTH SIDE 2025	الاطار الخلفي
06.C Rims Condition	MINOR DENT SCRATHES	حالة الجنوط
07 Suspension System		ممتص الصدمات
07.A Arms	BUSHES CRACK	ازرع
08 Interior Condition		الحالة الداخلية
08.A Other	INTERIOR PARTS GETTING RUSTY	اخرى
08.B AC Condition	NOT CHECK	المكيف
08.C Door Panel	WORN OUT	لوحة بطانة الباب
08.D Steering Wheel and control buttons	WORN OUT	عجلة القيادة وازرار التحكم
08.E Gear Shifting Lever	WORN OUT	ذراع نقل السرعات

you can verify the validity of the certificate via the link: carcheck.ae/certificate



يمكنك التحقق من صحة الشهادة عبر الرابط carcheck.ae/certificate

Terms & Conditions

الشروط والأحكام

The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.

شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.

Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.

كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

For complaints and inquiries reach out to us on wecare@carscheck.ae

للسكاوي والمقترحات يمكنك التواصل معنا عبر wecare@carscheck.ae