



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	23 Jan 2023, 15:52:44
Transaction Number	27282681 (CC10010)	Queue Number	657837



Chassis Number	VF3WC5FWF9W001745
Engine Number	
Vehicle Class	Car
Manufacturer	Peugeot
Model	207
Model Year	2009
Color	Silver
Mileage	188526 Km
Fuel Type	Petrol
No. Of Cylinders	4
Specification	GCC Specification

DEFECT	REMARKS	
01 Interior Condition		الحاله الداخليه
01.A Steering Wheel and control buttons	WORN OUT .	عجلة القيادة وازرار التحكم
01.B Door Panel	PORTION LOOSE .	لوحة بطانة الباب
01.C Power Window Switch	MAIN SWITCH BUTON LOOSE ,REAR LEFT SIDE NOT WORKING .	مفتاح النافذه
01.D AC Condition	OK	المكيف
01.E Dash Board	GLOVE BOX LOCK DAMAGED ,LOOSE .	لوحة القيادة
01.F Mirror	REAR VIEW MIRROR FADED	المرايا
01.G Sun Visor	LOOSE .	حاجب الشمس
02 Body		جسم المركبة
02.A Bonnet	MISALIGN	غطاء المحرك
02.B Bumper	MISALIGN,PORTION DAMAGED	دعامية
02.C Paint	BODY PORTION REPAIRED , REPAINTED & MINOR DENT ,SCRATCHES,PORTION FADED,	الصبغ
02.D Floor	PORTION DENT	الارضية
02.E Sign of back accident		وجود مؤشر لحادث في الخلف
02.F Doors	REAR DOORS LOOSE .	أبواب

DEFECT	REMARKS	
02.G Other	REAR BUMPER FRAME,BACK PANEL,CRASH BOX,SPARE WHEEL HOUSING REPAIRED,BEND	اخرى
02.H Rusty	UNDER BODY PARTS SUSPENSION GETTING RUSTY	صدأ
03 Suspension System		ممتص الصدمات
03.A Shock Absorber	LEAK,WEAK	ممتص الصدمات
03.B Arms	LOWER ARM BUSH CRACKED	ازرع
04 Lights		الاضاءة
04.A Head Light	LENS FADED.	الاضاءة الرئيسية
04.B Brake Light	NOT WORKING	نور الفرامل
05 Transmission Condition		الجير
05.A Visual Gear Box Condition	REFITTED,OIL LEAK,JERKING	حالة الجير النظري
06 Engine Condition		المحرك
06.A Smoke	WHITE SMOKE	دخان
06.B Visual Engine Condition	REFITTED,OIL LEAK,ABNORMAL NOISY	حالة المحرك النظري
07 Chassis Condition		النشاصي
07.A Chassis	CHECKED VISIBLE AREA OK	النشاصيه
08 Brake Condition		الفرامل
08.A Hand Brake	WEAK	فرامل اليد
08.B Brake Pedal	HARD	دواسة الفرامل
09 Tires and Rims Condition		الاطارات
09.A Front Tyre	BOTH SIDE 2017 CRACKED , EXPIRED	الاطار الامامي
09.B Rear Tyre	BOTH SIDE 2017 CRACKED , EXPIRED	الاطار الخلفي

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص في هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.