



TEST CERTIFICATE

Site Number	840-Emirates Auctions	Transaction Date	28 Aug 2022, 10:36:51
Transaction Number	74701482 (CC10006)	Queue Number	312309



Chassis Number	1FATP8FF9F5346035
Engine Number	
Vehicle Class	Car
Manufacturer	Ford
Model	Mustang
Model Year	2015
Color	Orange
Mileage	175924 Km
Fuel Type	Petrol
No. Of Cylinders	8
Specification	GCC Specification

DEFECT	REMARKS	
01 Body		جسم المركبة
01.A Doors	LEFT SIDE PORTION REPAIRED,REPAINTED	أبواب
01.B Bonnet	PORTION REPAIRED,REPAINTED & REFITTED	غطاء المحرك
01.C Sign of front accident		وجود مؤشر لحادث في المقدمة
01.D Bumper	FRONT BUMPER FRAME ,BULKHEAD ,RADIATOR SUPPORT ,CROSS MEMBER REPAIRED. MISS ALIGNED	دعامية
01.E Paint	BODY PORTION REPAINTED,PORTION REPAIRED,MINOR DENT,SCRATCHES	الصبغ
01.F Rusty	UNDER BODY SUSPENSION PARTSGETTING RUSTY .	صدأ
01.G Fenders	FRONT BOTH SIDE REPAINTED , REFITTED & REAR LEFT SIDE PORTION REPAIRED, REPAINTED	مدكار
02 Interior Condition		الحالة الداخلية
02.A AC Condition	OK	المكيف
03 Exhaust System		نظام العادم
03.A Modification	MODIFIED ,REWELDED.	تعديلات
04 Tires and Rims Condition		الاطارات
04.A Rear Tyre	LEFT SIDE 12018 .RIGHT SIDE 2021	الاطار الخلفي

DEFECT	REMARKS	
04.B Front Tyre	LEFT SIDE 2021 .RIGHT SIDE 2019 WORN OUT	الاطار الامامي
05 Lights		
05.A Head Light	LENS FADED.	الاضاءة الرئيسية
06 Transmission Condition		
06.A Road Test	NOT CHECK	فحص علي الطريق
06.B Visual Gear Box Condition	OK	حالة الجير النظرى
07 Engine Condition		
07.A Visual Engine Condition	OIL LEAK	حالة المحرك النظرى
08 Suspension System		
08.A Arms	LOWER ARM BUSHES CRACKED	ازرع
08.B Ball Joint	BALL JOINT BOOT CUT	مفصل كروي
09 Chassis Condition		
09.A Chassis	FRONT RIGHT SIDE CHASSIS REPAIRED	الشاسيه

- The inspection report is valid and shows the vehicle's condition at the time of the inspection only. Car Check doesn't guarantee the vehicle's condition as soon as it leaves the inspection station, and from then on, the inspection is considered invalid.
- Car Check is not responsible for hidden defects of the vehicle, and according to this certificate, Car Check does not guarantee the vehicle's fitness for registration.



- شهادة الفحص سارية وتظهر حالة المركبة وقت الفحص فقط، ولا تضمن كار تشيك حالة المركبة بمجرد خروجها من محطة الفحص، ويعتبر الفحص فى هذه الحالة غير ساري.
- كار تشيك غير مسؤولة عن العيوب الخفية في المركبة، كما لا تضمن بموجب هذه الشهادة صلاحية المركبة للتسجيل من عدمه.

Test Certificate



Vehicle
Registration



X FAILED

Plate Details :	W 45189 Dubai Private
Chassis No :	1FATP8FF9F5346035
Vehicle Make :	FORD
Vehicle Model :	MUSTANG
Vehicle Class :	Light Vehicle
Body Type :	Coupe
Fuel :	Benzene
Color :	Orange
Drive Direction :	--
Dimensions : (H x W x L)	-- x -- x --
Current Odometer :	178929 Kms.
Origin : United States	Model Year : 2015
Gear Type : Automatic	Engine Size : 5000 CC
Engine No : F5346035	Horse 435
Axles No : 2	Power :
No Of 2	Cylinders : 8
Doors :	No Of Seats : 4
G. V. W. : 2100 Kgs.	Empty 1637 Kgs.
	Weight :

⚠ Retest can be done only in Dubai

Certificate Number :	5-TAS-2022-17736966		
Inspection Date :	28-09-2022		
Certificate Print Date :	28-09-2022		
Services :	Registration Test		
Vehicle Testing Partner :	Tasjeel		
Vehicle Testing Center :	Tasjeel Al Aweer		
Total Time Taken :	10 min 54 sec		
Appointment Ref Number :	--		
Start Time :	16:53	End Time :	17:04
Lane :	01	Token No. :	185
Attempt :	1	Prints No. :	1

Parameter Readings

Service brake imbalance on front axle	Service brake imbalance on rear axle	Parking brake imbalance between LHS and RHS	Vehicle on Petrol CO Reading
14 %	6 %	14 %	0 %
Vehicle on Petrol HC Reading			
3 PPM VOL			

Inspection Findings

Defects	Issue	Severity
Steering Boots and Ball Joints CHANGE FRONT RIGHT SIDE LOWER BALL JOINT WORN	Loose or defective ball joint(s)	Major
Tire CHANGE 2 TIRES FRONT RIGHT SIDE&REAR LEFT SIDE WORN OUT	Worn out tread tire	Major

Inspection Remarks:

EXHAUST MODIFIED/ NOT NOISY/FRONT RIGHT SIDE CHASSIS HEATED REPAIRED STILL BEND HAVE PASS C.C.M REPORT CAR-O-LINER WORK ORDER# 135107 (25-07-2016). FRONT BUMPER FRAME, BULK HEAD OLD REPAIRED.

Payment Details

Inspection Performed by	Payment Method	Transaction Number	Service Fees
3104	Cash	17736966	AED 170 Collected on 28/09/2022
Parking Slot No	Service Name	Attempt	Received by
--	Registration Test	1	Sittu Paloth Sreesan Paloth

ⓘ This is to acknowledge the receipt of AED 170 (in words: One Hundred and Seventy Dirhams Only.), towards the above service.

ⓘ Information in this certificate regarding the annual consumption rate of the vehicle is based on estimated calculations.

تستخدم هذه الشهادة حصرا في العمليات الخاصة بالتسجيل الفنى للمركبة. لا يعتد بهذه الشهادة لأي عمليات أخرى بما في ذلك أغراض البيع أو الشراء خلاف عملية ترخيص المركبة. لا تتحمل الجهة المصدرة أية مسؤولية جراء استعمال هذه الشهادة لغير ما أصدرت من أجله. هذه الشهادة صالحة لإجراء معاملة واحدة فقط خلال 30 يوم من تاريخ الفحص.

This certificate is used exclusively in the technical licensing process for vehicle. This certificate should not be valid for any process including selling or buying purposes other than vehicle licensing process. The issuing entity shall not bear any liability for using this certificate for any purposes other than those it was issued for. This certificate is valid for one transaction only for 30 days from the date of inspection.

